


	<h2 style="color: #E67E22;">S-80913CLNB-G6HT2U</h2>
	<p>Manufacturer Part Number: S-80913CLNB-G6HT2U</p> <hr/> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <hr/> <p>Part of Description: IC VOLT DETECTOR 1.3V SC-82AB</p> <hr/> <p>Datasheets:  S-80913CLNB-G6HT2U.pdf</p> <hr/> <p>RoHs Status:  Lead free / RoHS</p> <hr/> <p>Stock Condition: Compliant New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	S-80913CLNB-G6HT2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.3V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	2.7 ms Minimum
Voltage - Threshold	1.3V
Packaging	Tape & Reel (TR)

S-80913CLNB-G6HT2U is New Original in Stock, Search S-80913CLNB-G6HT2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80913CLNB-G6HT2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80913CLNB-G6HT2U : Info@Y-IC.com



















































You May Be Also Be interested

In:

 <p>S-80913CLPF-G6HTFU SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SNT-4A</p>	 <p>S-80913ALMP-DAAT2G SEIKO S-80913ALMP-DAAT2G SEIKO</p>	 <p>S-80913CLPF-G6HTFG SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SNT-4A</p>	 <p>S-80913CLMC-G6HT2U SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>
 <p>S-80913CLMC-G6HT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p>S-80913CNMC-G8HT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p>S-80913CNMC SEIKO S-80913CNMC SEIKO</p>	 <p>S-80913CNMC-G8HT2U SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>

Hot Parts

More

- | | | | | |
|--|---|---|---|--|
|  2DI75A-120A |  AD22264S1 |  AS3-15-24 |  BR1102W-640-TR |  BTN3904N3 |
|  C2012X7R2E103M125AE |  CIH03Q5N1CNC |  CY62148CV30LL-70BAI |  CY8C21323-24PVXI |  DDZ8V2BSF-7 |
|  DF400R07PE4R_B6 |  DSD17-02B |  DT162N08KOF |  GRM0336R1E7R1CD01D |  GRM2165C1H100F201D |
|  GS1008CHGR-R10K-100N |  GS4982-CTAE3 |  IPD65R380E6 |  IS24C01B-2GLI |  LD025A150JAB2A |
|  LM385LPE3-2-5 |  LT1027DCS8-5 |  LT1964ES5-5 |  LV16003MHX/NOPB |  M1MA151WK |
|  MAX1162CCUB+T |  MAX15005BAUE |  MAX3243ECDB |  MAX3318CPWR |  MAX6328UR23 |
|  MIG100J6CCSB1W |  NCP5111DR2G |  RT9025-25PSP |  RT9199GS |  SD3000C04K |
|  SKKL92/16D |  SMCJ7.5CA-E3/57 |  SN74ABT18502APM |  SPX431AM1-L/TR |  STI1160A2 |
|  SUM110N10-09-E3 |  SY89853UMG |  TCTALOE337M8R-E1 |  TLE2064CDRG4 |  TLZ13B-GS08 |
|  V12P10-M3/86A |  VI-J6Y-CX/F7 |  VUO80/16N01 |  W25B40VNIG |  WL1251BZQZR |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited