










	SY89823LHI
	Manufacturer Part Number: SY89823LHI
	Manufacturer/Brand: Micrel / Microchip Technology
	Part of Description: IC CLK BUFFER 2:22 500MHZ 64TQFP
<p>Image may be representation. See specs for product details.</p>	Datasheets:  SY89823LHI.pdf
	RoHs Status: Contains lead / RoHS non-compliant
	Stock Condition: New original, 550 pcs Stock Available.
	Ship From: Hong Kong
	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	SY89823LHI
Manufacturer	Micrel / Microchip Technology
Description	IC CLK BUFFER 2:22 500MHZ 64TQFP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	550 pcs Stock
Series	Precision Edge®
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer, Translator
Frequency - Max	500MHz
Package / Case	64-TQFP Exposed Pad
Supplier Device Package	64-EP-TQFP
Number of Circuits	1
Voltage - Supply	3.15 V ~ 3.45 V
Output	HSTL
Input	HSTL, LVPECL
Ratio - Input:Output	2:22
Differential - Input:Output	Yes/Yes
Packaging	Tray

SY89823LHI is New Original in Stock, Search SY89823LHI Datasheets, PDF, Inventory at Y-IC.com Online, Order SY89823LHI Micrel / Microchip Technology with warrantied and confidence. RFQ SY89823LHI : Info@Y-IC.com

You May Be Also Be interested In:

 <p>SY89823LHI-TR Micrel / Microchip Technology IC CLK BUFFER 2:22 500MHZ 64TQFP</p>	 <p>SY89809LTH TR MIC MIC SY89809LTH TR MIC</p>	 <p>SY89824LHC Micrel / Microchip Technology IC CLK BUFFER 2:22 64TQFP</p>	 <p>SY89824LHC-TR Micrel / Microchip Technology IC CLK BUFFER 2:22 64TQFP</p>
 <p>SY89823LHY-TR Micrel / Microchip Technology IC CLK BUFFER 2:22 500MHZ 64TQFP</p>	 <p>SY89823LHG Micrel / Microchip Technology IC CLK BUFFER 2:22 500MHZ 64TQFP</p>	 <p>SY89809LTH Micrel / Microchip Technology IC CLK BUFFER 2:9 500MHZ 32TQFP</p>	 <p>SY89809LTH-TR Micrel / Microchip Technology IC CLK BUFFER 2:9 500MHZ 32TQFP</p>

Hot Parts

More

- | | | | | |
|------------|---------------|--------------|--------------|----------------|
| SY89329VMI | SY89420VJZ | SY89421VZC | SY89421VZH | SY89429AJC |
| SY89429VJC | SY89429VZC | SY89429VZH | SY89430VJC | SY89430VJZ |
| SY89430VZH | SY89474UMG-TR | SY89529LTC | SY89530LZC | SY89531LHC |
| SY89532LHC | SY89537LMG | SY89538LHH | SY89547LMG | SY89547LMGTR |
| SY89645L | SY897132L | SY89809L | SY89809LTC | SY89809LTH |
| SY89823LHY | SY89824LHC | SY89824LHZ | SY89824LHZTR | SY89825UHI |
| SY89825UHY | SY89826LHG | SY89826LHI | SY89826LHY | SY89827LHI |
| SY89828CHY | SY89828LHY | SY89829UHY | SY89830UK4G | SY89830UK4G-TR |
| SY89831U | SY89831UMG | SY89831UMGTR | SY89831UMI | SY89831UMITR |
| SY89832UMG | SY89832UMGTR | SY89832UMI | SY89833ALMI | SY89833L |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited