



|   |   |
|---|---|
|  | <p><b>LA4461N</b></p>   |
|   | <p><b>Manufacturer Part Number:</b> LA4461N</p> <p><b>Manufacturer/Brand:</b> SANYO</p> <p><b>Part of Description:</b> SANYO SIP-10P</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 6000 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation.<br/>See specs for product details.</p>            |   |

| Specifications |   |
|----------------|---|
| Part Number    | LA4461N   |
| Manufacturer   | SANYO   |
| Description    | SANYO SIP-10P                                   |
| Category       | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status    | 6000 pcs Stock                                  |
| Series         | -   |
| RoHs Status    | Lead free / RoHS Compliant                      |
| Condition      | New Original Stock                              |
| Warranty       | 100% Perfect Functions                          |
| Lead Time      | 2-3days after payment.                          |
| Payment        | PayPal / Telegraphic Transfer / Western Union   |
| Shipping by    | DHL / Fedex / UPS                               |
| Port           | HongKong  |
| RFQ Email      | Info@Y-IC.com                                   |

LA4461N is New Original in Stock, Search LA4461N Datasheets, PDF, Inventory at Y-IC.com Online, Order LA4461N with warranted and confidence. RFQ LA4461N : Info@Y-IC.com

You May Be Also Be interested

In:

|  |   |  |   |
|--|---|--|---|
|  <p><b>LA4450-E</b><br/>AMI Semiconductor / ON<br/>Semiconductor<br/>IC AF PWR AMP 2CH 12W 20W<br/>SIP14H</p> |  <p><b>LA4485</b><br/>SANYO<br/>LA4485 SANYO</p> |  <p><b>LA4465</b><br/>SANYO<br/>LA4465 SANYO</p>   |  <p><b>LA4450F-E</b><br/>AMI Semiconductor / ON<br/>Semiconductor<br/>IC AUDIO AMPLIFIER 2CH 14SIP</p> |
|  <p><b>LA4460</b><br/>SANYO<br/>LA4460 SANYO</p>  |  <p><b>LA4485T</b><br/>SANYO<br/>SANYO ZIP</p>   |  <p><b>LA4460N</b><br/>SANYO<br/>SANYO ZIP-10P</p> |  <p><b>LA4471</b><br/>SANYO<br/>LA4471 SANYO</p>   |

Hot Parts

More

- |                      |                      |                      |                  |                   |
|----------------------|----------------------|----------------------|------------------|-------------------|
| ⊕ 1206CA680JAT1A     | ↔ 1812CC472KAT1A     | ⇒ 6R1T30Y-080        | D 7MBR75VR120-56 | ⇒ ACM2012-900-2P  |
| ⊖ AD7893AR-2-REEL    | ⊕ ADM811TART-REEL-7  | D AP4543GEH-HF       | ⇒ AT28C64B-25PU  | ⇒ BZX84C27        |
| ⊕ DAC34SH84IZAYR     | ⊖ DG409DYZ+T         | ⊕ DS32KHZSN#T        | ↔ FM30TF-10S     | ⇒ FQP17N08L       |
| D GCM0335C1E100JD03D | ⊕ GRM1555C1E4R4BA01D | ⊖ GRM31MR71E105KC01L | ⊕ GS9020PSF      | ⇒ IS42S16400B-6TL |
| ⇒ KSZ8995XA          | ↔ LD06CC153KAB1A     | ⊕ LMP2022MMX/NOPB    | ⊖ LMV344MTX/NOPB | ⇒ LTC1144CS8      |
| ↔ LTC3406AIS5        | ⇒ LTC6652BHMS8-2.5   | D M74HC14RM13TR      | ⊕ MA4X17400L     | ⊖ MAX4513CSE      |
| ⊕ MCP1603BT-330I/OS  | D MDI5N50TH          | ⇒ MJD44H11T4         | ↔ SA53776255     | ⇒ SD500N30MCPBF   |
| ⊖ SI4686DY-T1-GE3    | ⊕ SKDH60/04          | ↔ STK0765BF          | ⇒ SUM50P10-42-E3 | ⇒ SVC276-TL-E     |
| ⊕ T178N12TOF         | ⊖ TC2015-2.7VCTTR    | ⊕ TDA8002BT/5        | D TV918-1500-24  | ⇒ USR120PP12B     |
| ↔ VMM45-02FS         | ⊕ XC2S50-5PQG208C    | ⊖ XC61CC1702MR       | ⊕ ZXT1053AKTC    | ⇒ ZXTP25140BFHTA  |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited