


	PCK3807AD,112
	Manufacturer Part Number: PCK3807AD,112
	Manufacturer/Brand: NXP Semiconductors / Freescale
	Part of Description: IC CLK BUFFER 1:10 400MHZ 20SO
Datasheets:	 PCK3807AD,112.pdf
RoHS Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	


Specifications

Part Number	PCK3807AD,112
Manufacturer	NXP Semiconductors / Freescale
Description	IC CLK BUFFER 1:10 400MHZ 20SO
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	400MHz
Package / Case	20-SOIC (0.295", 7.50mm Width)
Supplier Device Package	20-SO
Number of Circuits	1
Voltage - Supply	2.3 V ~ 3.6 V
Output	LVTTTL
Input	LVC MOS, LVTTTL
Ratio - Input:Output	1:10
Differential - Input:Output	No/No
Packaging	Tube


PCK3807AD,112 is New Original in Stock, Search PCK3807AD,112 Datasheets, PDF, Inventory at Y-IC.com Online, Order PCK3807AD,112 NXP Semiconductors / Freescale with warrantied and confidence. RFQ PCK3807AD,112 : Info@Y-IC.com

You May Be Also Be interested


In:




PCK3807AD
NXP
NXP SOP20




PCK351D,118
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 125MHZ
24SO




PCK351D,112
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 125MHZ
24SO




PCK3807AD,118
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 400MHZ
20SO




PCK3807ADS,112
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 400MHZ
20SSOP



PCK3807ADB,112
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 400MHZ
20SSOP



PCK3807ADB,118
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 400MHZ
20SSOP



PCK351DB,118
NXP Semiconductors / Freescale
IC CLK BUFFER 1:10 125MHZ
24SSOP

Hot Parts

More

- | | | | | |
|----------------------|----------------------|--------------------|----------------------|----------------------|
| ⊗ 04023G103ZAT2A | ↔ 12063A562GAT2A | ⇒ 2220WC822KAT1A | D AD7576JN | ↗ ADM1025ARQZ-REEL7 |
| ⊣ AOZ8308SO-02 | ⊗ AP6209-33GA | D CD40106BCN | ⇒ CDRH73NP-3R3NC | ↗ CGRM4001-G |
| ⊗ CY7C291AL-35WC | ⊣ DKW1215D-2W | ⊗ FMMT591ATC | ↔ GCM2195G1H682JA16D | ↗ GRM1556T1H1R5CD01D |
| D IL400-X017T | ⊗ IRKH56/04 | ⊣ ISL6520BCB | ⊗ LD055A181JAB2A | ↗ LM63CIMAX-NOPB |
| ⇒ LT1167IS8 | ↔ MAX4684ETB+T | ⊗ MC9S08SE8VTG | ⊣ MIC2204BMM | ↗ NE57811S/G |
| ↔ NSS200-50 | ⇒ NTMFS4834NT1G | D NTMSD2P102LR2 | ⊗ PEB4165TV1.0 | ⊣ RA35H1516M |
| ⊗ S-1122B33MC-L8S-TF | D S-1170B36PD-OTVTFG | ⇒ SA521890 | ↔ SI2156-B30-GM | ↗ SMA6J18A-TR |
| ⊣ SMAJ12A-TR | ⊗ SS2H9-E3/5BT | ↔ SSM4509GM | ⇒ STA02713TR/STA027 | ↗ SUP38L6V2 |
| ⊗ SW10HHR400 | ⊣ TA48018F | ⊗ TBU-CA050-500-WH | D TDA16810G | ↗ TLC2252CPW |
| ↔ TCMCMC1C336MTR | ⊗ TMP01FPZ | ⊣ UMK105CG020BV-F | ⊗ V48C3V375BL2 | ↗ VN0550N3 |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited