

	<h2 style="color: #E67E22;">MAX6377XR29+T</h2>	
	Manufacturer Part Number:	MAX6377XR29+T
	Manufacturer/Brand:	Maxim Integrated
	Part of Description:	IC VOLT DETECT LP 2.93V SC70-3
Datasheets:	1.MAX6377XR29+T.pdf 2.MAX6377XR29+T.pdf	
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	MAX6377XR29+T
Manufacturer	Maxim Integrated
Description	IC VOLT DETECT LP 2.93V SC70-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-70, SOT-323
Supplier Device Package	SC-70-3
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	20 μs Typical Propagation Delay
Voltage - Threshold	2.93V
Packaging	Tape & Reel (TR)

MAX6377XR29+T is New Original in Stock, Search MAX6377XR29+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6377XR29+T Maxim Integrated with warrantied and confidence. RFQ MAX6377XR29+T : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MAX6377XR29-T Maxim Integrated IC VOLT DETECTOR LP 2.93V SC70-3</p>	 <p>MAX6377XR27+T Maxim Integrated IC VOLT DETECT LP 2.70V SC70-3</p>	 <p>MAX6377XR31+ Maxim Integrated IC VOLT DETECT LP 3.08V SC70-3</p>	 <p>MAX6377XR30-T Maxim Integrated IC VOLT DETECTOR LP 3.00V SC70-3</p>
 <p>MAX6377XR29 MAXIM MAXIM 3SC70</p>	 <p>MAX6377XR30+T Maxim Integrated IC VOLT DETECT LP 3.30V SC70-3</p>	 <p>MAX6377XR28-T Maxim Integrated IC VOLT DETECTOR LP 2.80V SC70-3</p>	 <p>MAX6377XR31 MAXIM MAXIM SOT23</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------|-------------------|----------------|--------------------|---------------------|
| 02013A0R7BAT2A | 1206YC106MAT2A | 12102C562JAT2A | D 2D09-33UH | ACE1101BEMT8 |
| AD6438BST | AT17LV010-10JC | AZ1085T-1.5 | B10B-ZR-SM4-TF | B2B-PH-SM4-TB.LF.SN |
| BAT54A-E3-08 | BD8100YS_L2_00001 | BSZ240N12NS3G | BZX84C3V9LT1G | DMG8880LK3-13 |
| FDMC7678 | FIN1108MTDX | FM24C128 | GRM0336R1E130JD01D | GRM188R61E475KE11J |
| HS16-102 | ICS1893AF | IP4281CZ10 | IRF7832U | ISL83384ECBZ |
| KP1000A4500V | KSA1182YM | LD2985BM30R | LM2724MX/NOPB | LM3622AMX-4.2 |
| LM5574QMTX/NOPB | MAX9113EKA | NCP1215DR2 | NCP1606DR2G | P6SMB13AT3 |
| PK2504B80 | PZU9.1B3 | RB068L100GTE25 | S-1132B20-M5T1G | SN74ALS08DR |
| SRV05-4.TCT | TC1303C-ZA0EMF | THS6204IRHFRG4 | TL322IDR | TPS79628DRBT |
| TPSMA24A-E3/61T | VI-J11-05 | VI-J61-EY | WG20038SP | XC61FS1YXXMR |