










	<b>BA5984FP-E2</b>
	<b>Manufacturer Part Number:</b> BA5984FP-E2
	<b>Manufacturer/Brand:</b> LAPIS Semiconductor
	<b>Part of Description:</b> IC BRIDGE DRIVER PAR 28HSOP
<b>Datasheets:</b>  BA5984FP-E2.pdf	<b>RoHs Status:</b>  Lead free / RoHS Compliant
<b>Stock Condition:</b> New original, 28376 pcs Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	BA5984FP-E2
Manufacturer	LAPIS Semiconductor
Description	IC BRIDGE DRIVER PAR 28HSOP
Category	Integrated Circuits (ICs) > PMIC - Full, Half-Bridge
Part Status	28376 pcs Stock
Series	-
Technology	Bipolar
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Features	-
Interface	Logic
Applications	DC Motors, General Purpose
Package / Case	28-SOP (0.295", 7.50mm Width) + 2 Heat Tabs
Supplier Device Package	28-HSOP
Voltage - Supply	4.3 V ~ 13.2 V
Current - Output / Channel	1A
Current - Peak Output	-
Output Configuration	Half Bridge (10)
Fault Protection	Over Temperature, UVLO
Load Type	Inductive
Rds On (Typ)	-
Voltage - Load	6V
Packaging	Original-Reel®










BA5984FP-E2 is New Original in Stock, Search BA5984FP-E2 Datasheets, PDF, Inventory at Y-IC.com Online, Order BA5984FP-E2 LAPIS Semiconductor with warrantied and confidence. RFQ BA5984FP-E2 : Info@Y-IC.com

### You May Be Also Be interested In:

 <p><b>BA5983FP-E2</b> LAPIS Semiconductor IC BRIDGE DRIVER PAR 28HSOP</p>	 <p><b>BA5985FM-DE2</b> ROHM BA5985FM-DE2 ROHM</p>	 <p><b>BA5985FM</b> ROHM BA5985FM ROHM</p>	 <p><b>BA5984FP</b> ROHM BA5984FP ROHM</p>
 <p><b>BA5984FP-E2.</b> LAPIS Semiconductor BA5984FP-E2. ROHM</p>	 <p><b>BA5983FM</b> ROHM BA5983FM ROHM</p>	 <p><b>BA5985FM-E2</b> ROHM BA5985FM-E2 ROHM</p>	 <p><b>BA5983FP</b> ROHM BA5983FP ROHM</p>

### Hot Parts

More

- |  |   |  |  |   |
|--|---|--|--|---|
|  BA5937AFP-E2 |  BA5937AFP-FE2 |  BA5937FP     |  BA5937FP-E2 |  BA5938FM    |
|  BA5938FM-E2  |  BA5941FP      |  BA5941FP-E2  |  BA5944FP-E2 |  BA5946FP    |
|  BA5946FP-E2  |  BA5947FM      |  BA5947FM-E2  |  BA5947FP-E2 |  BA5948FP    |
|  BA5949FP-E2  |  BA5952AFP     |  BA5954BFP-E2 |  BA5954FM    |  BA5954FM-E2 |
|  BA5954FP     |  BA5954FP-E2   |  BA5956FM-E2  |  BA595E6327  |  BA5960FS-E2 |
|  BA5962FVM    |  BA5962FVM-FTR |  BA5962FVM-TR |  BA5965FV-E2 |  BA5968FP-E2 |
|  BA5970FP     |  BA5970FP-E2   |  BA5972AFP-E2 |  BA5972FP    |  BA5972FP-E2 |
|  BA5974FM     |  BA5974FP      |  BA5974FP-E2  |  BA5982FP    |  BA5982FP-E2 |
|  BA5983FM     |  BA5983FM-E2   |  BA5983FP     |  BA5983FP-E2 |  BA5984FP    |
|  BA5985FM     |  BA5985FM-DE2  |  BA5986FM-E2  |  BA5995FM-E2 |  BA5996FM-E2 |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited