



	<h2 style="color: #e67e22;">R5F100GKANA#U0</h2>	
	Manufacturer Part Number:	R5F100GKANA#U0
	Manufacturer/Brand:	Renesas Electronics America
	Part of Description:	IC MCU 16BIT 384KB FLASH 48HWQFN
	Datasheets:	 1.R5F100GKANA#U0.pdf  2.R5F100GKANA#U0.pdf
	RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	









Specifications

Part Number	R5F100GKANA#U0
Manufacturer	Renesas Electronics America
Description	IC MCU 16BIT 384KB FLASH 48HWQFN
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	RL78/G13
Operating Temperature	-40°C ~ 85°C (TA)
Package / Case	48-WFQFN Exposed Pad
Supplier Device Package	48-HWQFN (7x7)
Peripherals	DMA, LVD, POR, PWM, WDT
Core Processor	RL78
Speed	32MHz
Number of I/O	34
EEPROM Size	-
RAM Size	24K x 8
Core Size	16-Bit
Connectivity	CSI, I ² C, LIN, UART/USART
Program Memory Size	384KB (384K x 8)
Program Memory Type	FLASH
Voltage - Supply (Vcc/Vdd)	1.6 V ~ 5.5 V
Data Converters	A/D 10x8/10b
Oscillator Type	Internal
Packaging	Tray

R5F100GKANA#U0 is New Original in Stock, Search R5F100GKANA#U0 Datasheets, PDF, Inventory at Y-IC.com Online, Order R5F100GKANA#U0 Renesas Electronics America with warrantied and confidence. RFQ R5F100GKANA#U0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>R5F100GJGFB#V0 Renesas Electronics America 16BIT MCU RL78/G13 256K LFQFP48</p>	 <p>R5F100GLANA#U0 Renesas Electronics America IC MCU 16BIT 512KB FLASH 48HWQFN</p>	 <p>R5F100GKAFB#V0 Renesas Electronics America IC MCU 16BIT 384KB FLASH 48LFQFP</p>	 <p>R5F100GLAFB#V0 Renesas Electronics America IC MCU 16BIT 512KB FLASH 48LFQFP</p>
 <p>R5F100GLANA#W0 Renesas Electronics America IC MCU 16BIT 512KB FLASH 48HWQFN</p>	 <p>R5F100GJGFB#X0 Renesas Electronics America 16BIT MCU RL78/G13 256K LFQFP48</p>	 <p>R5F100GLAFB#X0 Renesas Electronics America IC MCU 16BIT 512KB FLASH 48LFQFP</p>	 <p>R5F100JCAFA#V0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 52LQFP</p>

Hot Parts

More

- | | | | | |
|--------------------|----------------------|--------------------------|-----------------------|-----------------------|
| ⊛ 04023C152KAJ2A | ↔ 06033C222J4T2A | ⇒ 12107A152KAT2A | D 181RKI100 | ⇒ A50L-0001-0212 |
| ⊣ AD7928BRUZ-REEL7 | ⊛ AD9852ASQZ | D ADM1181AARZ | ⇒ ADM4856ARZ | ⇒ AOZ2262QI-18 |
| ⊛ AP6213A-30NHFGA | ⊣ AS7C34098A-12TCN | ⊛ BSL215CH6327 | ↔ C2012X7R1V105K125AB | ⇒ CSMH2-30MTR13 |
| D CP7270BT | ⊛ CYD25-24S05J | ⊣ DTC115EKA | ⊛ ETC9413FP | ⇒ FCAU3060A |
| ⇒ FDS6894A-NL | ↔ GRM0336S1E7R2DD01D | ⊛ GRM1886T1H7R9DD01D | ⊣ HAT1038RJ-EL | ⇒ ISL6353CRTZ |
| ↔ K9GAG08U0M-PIBO | ⇒ LQP03TN2N7B04D | D LTC2751AIUHF-16#TRPBF. | ⊛ M27C256B-12C1 | ⊣ MAX3491CSD |
| ⊛ MAX428CSA+T | D MB15F73ULPVA-G-EF | ⇒ MC10XS3435D | ↔ MCP6004I/ST | ⇒ MLX12103EB |
| ⊣ NCP1200AD100R2 | ⊛ NDT3055L | ↔ NTCG164BH222JT1 | ⇒ PQ012FZ012P | ⇒ SG2011-2.8XN3/TR |
| ⊛ SP60D-243315 | ⊣ STD12N65M5 | ⊛ STI7101SWD | D STPS30-45M | ⇒ SUD06N10-225L-T1-E3 |
| ↔ SUP90N08-6m8P | ⊛ T55B227M2R5C0070 | ⊣ TC74HC126A | ⊛ VI-J0L-IY | ⇒ VND10B-E |

Contact us: **Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited