









	<h2 style="color: red;">NN30312A-VB</h2>	
	Manufacturer Part Number:	NN30312A-VB
	Manufacturer/Brand:	Panasonic
	Part of Description:	IC REG BUCK ADJ 10A SYNC 40HQFN
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications	
Part Number	NN30312A-VB
Manufacturer	Panasonic
Description	IC REG BUCK ADJ 10A SYNC 40HQFN
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Voltage - Input (Max)	30V
Output Type	Adjustable
Package / Case	40-WFQFN Exposed Pad
Supplier Device Package	40-HQFN (6x6)
Function	Step-Down
Current - Output	10A
Frequency - Switching	250kHz, 750kHz, 1.25MHz
Number of Outputs	1
Output Configuration	Positive
Topology	Buck
Voltage - Output (Min/Fixed)	0.75V
Voltage - Output (Max)	5.5V
Synchronous Rectifier	Yes
Voltage - Input (Min)	4.5V
Packaging	Cut Tape (CT)

NN30312A-VB is New Original in Stock, Search NN30312A-VB Datasheets, PDF, Inventory at Y-IC.com Online, Order NN30312A-VB Panasonic with warrantied and confidence. RFQ NN30312A-VB : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>NN30295A-VB Panasonic IC REG BUCK ADJ 6A SYNC 24HVQFN</p>	 <p>NN30321A-VB Panasonic IC REG BUCK ADJ 6A SYNC 24QFN</p>	 <p>NN30310AA-EVB-R2 Panasonic BOARD EVAL FOR NN30310AA DC/DC</p>	 <p>NN30332A-VB Panasonic IC REG BUCK ADJ 10A SYNC 24QFN</p>
 <p>NN30331A-VB Panasonic IC REG BUCK ADJ 8A SYNC 24QFN</p>	 <p>NN30321A-EVB-R2 Panasonic BOARD EVAL FOR NN30321A DC/DC</p>	 <p>NN30310AAVB Panasonic IC REG BUCK ADJ 3A SYNC 24QFN</p>	 <p>NN30312A-EVB-R2 Panasonic BOARD EVAL FOR NN30312A DC/DC</p>

Hot Parts More

- | | | | | |
|---------------------|--------------------|----------------------|---------------------|----------------------|
| ⊛ 06033G333ZAT2A | ↔ 1-292141-6 | ⇒ 13001-S6D(6B) | D 1812AA561JAT3A\SB | ⇒ 293D225X9035C2TE3 |
| ⊣ ACPL-214-50AE | ⊛ ADG758BCPZ-REEL7 | D AP1501A-12 | ⇒ AP1701DWLA | ⇒ ATTINY44-20SSU |
| ⊛ AZ1084S2-ADJ | ⊣ BD6529GUL-E2 | ⊛ CD4029BE | ↔ DMNH4015SSDQ-13 | ⇒ DS1706REPA |
| D EP82562GT | ⊛ FAN5031MPX | ⊣ GCM1885C2A5R7DA16D | ⊛ GM8123-ISO | ⇒ HMC830LP6GE |
| ⇒ HMK107B7152KA-T | ↔ IMP8031MA-T | ⊛ K9GAG08UOM-PCB0 | ⊣ KQ324515 | ⇒ L09ESD3V3CA2 |
| ↔ L78L18AC-UTR | ⇒ LD031C822JAB2A | D LE88276DLC | ⊛ LQP15MN15NG00D | ⊣ LTC2051HVCS8#TRPBF |
| ⊛ MAX3443EASA+T | D MAX4717ETB | ⇒ MLG1005S3N9BT000 | ↔ MMSZ5258BS-TG | ⇒ N0646LC340 |
| ⊣ NCP1605ADR2G | ⊛ NTD95N02RT4G | ↔ PS21342-BNP | ⇒ PYD5731/3699 | ⇒ S-8244AAAFN |
| ⊛ SCY99185AMX130TCG | ⊣ SMCJ75CA-E3/57T | ⊛ ST180S20P0 | D TA48M02SF | ⇒ TLE4675G |
| ↔ TN1625-1000G | ⊛ U4283BM-BFLG3 | ⊣ V300B3V3T150AL | ⊛ V375A32C600BG4 | ⇒ WPT250-14 |