

 A Renesas Company	ISL6565BCV
	Manufacturer Part Number: ISL6565BCV
	Manufacturer/Brand: Intersil
	Part of Description: IC REG CTRLR BUCK 28TSSOP
	Datasheets:  ISL6565BCV.pdf
	RoHs Status: Contains lead / RoHS non-compliant
	Stock Condition: New original, 175 pcs Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL6565BCV
Manufacturer	Intersil
Description	IC REG CTRLR BUCK 28TSSOP
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	175 pcs Stock
Series	-
Operating Temperature	0°C ~ 105°C (TA)
Output Type	PWM Signal
Package / Case	28-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	28-TSSOP
Function	Step-Down
Frequency - Switching	80kHz ~ 1.5MHz
Number of Outputs	3
Output Configuration	Positive
Voltage - Supply (Vcc/Vdd)	4.75 V ~ 5.25 V
Topology	Buck
Control Features	Enable, Frequency Control, Power Good
Output Phases	3
Duty Cycle (Max)	66.7%
Synchronous Rectifier	-
Clock Sync	No
Serial Interfaces	-
Packaging	Tube

ISL6565BCV is New Original in Stock, Search ISL6565BCV Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6565BCV Intersil with warrantied and confidence. RFQ ISL6565BCV : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL6566ACRZ Intersil IC CTRLR PWM 3PHASE BUCK 40-QFN	 ISL6565BCRZ-T Intersil IC REG CTRLR BUCK 28QFN	 ISL6565BCR Intersil IC REG CTRLR BUCK 28QFN	 ISL6565BCVZ Intersil IC REG CTRLR BUCK 28TSSOP
 ISL6565BCR-T Intersil IC REG CTRLR BUCK 28QFN	 ISL6565BCRZ Intersil IC REG CTRLR BUCK 28QFN	 ISL6565BCV-T Intersil IC REG CTRLR BUCK 28TSSOP	 ISL6565BCVZ-T Intersil IC REG CTRLR BUCK 28TSSOP

Hot Parts

More

- | | | | | |
|-------------------------|---------------------|----------------------|------------------------|---------------------|
| ⊛ 0603ZC561KAT2A | ↔ 2MBI450U4E-120 | ⇒ AC0402FR-7W3K57L | D ADS7822U/2K5G4 | ⇒ AP393SG-13 |
| ⊣ AT-41411-TR1 | ⊛ BZT52C30S | D BZX384-B39.115 | ⇒ CGA5H4X7R2J472K115AA | ⇒ CNX35U300 |
| ⊛ FP25R12KT4_B13_EN | ⊣ FQB33N10LTM | ⊛ GQM1555C2D2R7CB01D | ↔ GRM1885C1H5R0CA01J | ⇒ HLB-50AP |
| D HP7501TG0-F-036AAA-LF | ⊛ IMIC9716IBT | ⊣ LH1509A4 | ⊛ LLL185C70G474MA01L | ⇒ LMSP430G-B31 |
| ⇒ LTC4309IGN#TRPBF | ↔ M5M5V408BFP-85H | ⊛ MA27V040P1TD | ⊣ MAX3318EEAP+T | ⇒ MBRB30H90CT-E3/81 |
| ↔ MC10109FNR2 | ⇒ MM3033DURE | D MP2633AGR-Z | ⊛ NLV32T-680J-PF | ⊣ NLV32T-R47J-PF |
| ⊛ P6KE47CA | D PFS7316V | ⇒ PIC12F510T-I/SN | ↔ PRME15119 | ⇒ PS11014-C |
| ⊣ S9S12XS128VAE | ⊛ SIL40C-12SADJ-HP4 | ↔ SKN2M130/18 | ⇒ SM4843NSK | ⇒ SMBZ5923B |
| ⊛ SN74AUP1G125DBVR | ⊣ ST1S12G12R | ⊛ ST24FC21B6 | D STPAC01F2AU | ⇒ T501N60TOH |
| ↔ TISP1089ASD-S | ⊛ TM150RZ-M | ⊣ TZMCS226B-GS08 | ⊛ VE-2N3-CX | ⇒ VI-B50-02 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited