

 A Renesas Company	ISL6398IRTZ-TK
	Manufacturer Part Number: ISL6398IRTZ-TK
	Manufacturer/Brand: Intersil
	Part of Description: IC REG CTRLR BUCK PMBUS 40QFN
Datasheets:	1.ISL6398IRTZ-TK.pdf
	2.ISL6398IRTZ-TK.pdf
RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL6398IRTZ-TK
Manufacturer	Intersil
Description	IC REG CTRLR BUCK PMBUS 40QFN
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Output Type	PWM Signal
Package / Case	40-VFQFN Exposed Pad
Supplier Device Package	40-TQFN (5x5)
Function	Step-Down
Frequency - Switching	120kHz ~ 2.025MHz
Number of Outputs	6
Output Configuration	Positive
Voltage - Supply (Vcc/Vdd)	4.75 V ~ 5.25 V
Topology	Buck
Control Features	-
Output Phases	6
Duty Cycle (Max)	98%
Synchronous Rectifier	No
Clock Sync	-
Serial Interfaces	I ² C, PMBus, SMBus
Packaging	Tape & Reel (TR)

ISL6398IRTZ-TK is New Original in Stock, Search ISL6398IRTZ-TK Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6398IRTZ-TK Intersil with warrantied and confidence. RFQ ISL6398IRTZ-TK : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL6398HRTZ Intersil IC REG CTRLR BUCK PMBUS 40QFN	 ISL6401CR Intersil IC REG CTRLR BOOST/FLYBACK 16QFN	 ISL6398HRTZ-TK Intersil IC REG CTRLR BUCK PMBUS 40QFN	 ISL6401CBZ Intersil IC REG CTRLR BOOST/FLYBK 14SOIC
 ISL6401CB Intersil IC REG CTRLR BOOST/FLYBK 14SOIC	 ISL6398HRTZ-T Intersil IC REG CTRLR BUCK PMBUS 40QFN	 ISL6398IRTZ-T Intersil IC REG CTRLR BUCK PMBUS 40TQFN	 ISL6401CBZ-T Intersil IC REG CTRLR BOOST/FLYBK 14SOIC

Hot Parts

More

- | | | | | |
|------------------|-----------------------|------------------------|-----------------------|-----------------|
| ⊛ 0603YC181MAT2A | ↔ 12061A821KAT4A | ⇒ AD7398BRU-REEL7 | D AK7754EN-L | ⇒ AUXCLFR5410 |
| ↳ BCP53-16/B | ⊛ BSP373NH6327 | D BZX79-B13 | ⇒ C4532X7T2E105MT000N | ⇒ CNY171300 |
| ⊛ CPL2510T4R7M | ↳ DMP3036SSD | ⊛ ETA5050S2F | ↔ FQA7N80C | ⇒ GDZT2R6.2 |
| D H11AA3SR2VM | ⊛ LDC15B190K0924H-027 | ↳ LT3008ETS8-2.5#TRPBF | ⊛ LT3757EMSE#TRPBF | ⇒ MAX208EAG-T |
| ⇒ MAX221EEAE+ | ↔ MAX9700CETB+T | ⊛ MBRM120ET3 | ↳ MP4021GS-A-Z | ⇒ N630CH30 |
| ↔ RN412HTTE200J | ⇒ RS3BHE3/57T | D S-80843ANNP-ED7-T2 | ⊛ S71PL129NCOHFW | ↳ SC6600I1-265G |
| ⊛ SC900739EK | D SI1405BDH-T1-GE3 | ⇒ SI3469DV-T1-E3 | ↔ SKMD150F08 | ⇒ SN65LVDS390DR |
| ↳ SN74LS374N | ⊛ SPX2810T-3.3/TR | ↔ SSM3J09FU | ⇒ TAQL155K010RTA | ⇒ TC74HC4053AFN |
| ⊛ TDA9181T/N1 | ↳ THS4522IPWR | ⊛ TISP5115H3BJR-S | D TK5A45DA | ⇒ TLV2474IDR |
| ↔ TMP125AIDBVR | ⊛ TRF370317IRGER | ↳ UMK105CH221JV-F | ⊛ VI-24L-MU | ⇒ VI-B60-38 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited