

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">3296Z-1-103LF</h2>
	<p>Manufacturer Part Number: 3296Z-1-103LF</p> <p>Manufacturer/Brand: BOURNS</p> <p>Part of Description: BOURNS DIP</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 10000 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	3296Z-1-103LF
Manufacturer	BOURNS
Description	BOURNS DIP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	10000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

3296Z-1-103LF is New Original in Stock, Search 3296Z-1-103LF Datasheets, PDF, Inventory at Y-IC.com Online, Order 3296Z-1-103LF with warrantied and confidence. RFQ 3296Z-1-103LF : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>3296Z-1-103 Bourns, Inc. TRIMMER 10K OHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-104LF Bourns, Inc. TRIMMER 100KOHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-101 Bourns, Inc. TRIMMER 100 OHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-103LF Bourns, Inc. TRIMMER 10K OHM 0.5W PC PIN SIDE</p>
 <p>3296Z-1-102 Bourns, Inc. TRIMMER 1K OHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-105LF Bourns, Inc. TRIMMER 1M OHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-101LF Bourns, Inc. TRIMMER 100 OHM 0.5W PC PIN SIDE</p>	 <p>3296Z-1-105 Bourns, Inc. TRIMMER 1M OHM 0.5W PC PIN SIDE</p>

Hot Parts

More

- | | | | | |
|--------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| ⚙️ 06035U390GAT2A | ➡️ 7MBI75N-060 | ➡️ BU9459KV | D CBS400B05 | ➡️ CC1210KX7R9BB475 |
| ⚡ CM20TF12H | ⚙️ CU4032K275G2 | D DDZ5V6BS-7 | ➡️ DM74AS258N | ➡️ FC13E-TL |
| ⚙️ FDFS2P106A | ⚡ GRM0225C1E101JA02L | ⚙️ GRM0335C1H1R7CA01D | ➡️ GRM0336T1E6R4CD01D | ➡️ H11C6-X006 |
| D H1205S-1W | ⚙️ HIP6004BCBZ-T | ⚡ HY2113-OB1C | ⚙️ INK0012AM1-T111-1 | ➡️ IR3541MSM02TRPBF-T |
| ➡️ IR3843AMTR1PBF. | ➡️ ISL28113FHZ-T7A | ⚙️ IXTP7P20 | ⚡ LD031A330FAB2A | ➡️ M0433WC180 |
| ➡️ MIC94050BM4 | ➡️ NLC565050T-101K-PF | D OPA657N/250G4 | ⚙️ P6KE8.2A-E3/73 | ⚡ PE-53683T |
| ⚙️ PZU5.1B1A | D SA85CA-E3/73 | ➡️ SC434209DW | ➡️ SI4866BDY-T1-GE3 | ➡️ SIS430DN-T1-GE3 |
| ⚡ SPUL409HE5H-PB-7 | ⚙️ ST8034TDT | ➡️ STM4437A | ➡️ SW1DG-H12C-4 | ➡️ TK10P60W |
| ⚙️ TPS7333QPW | ⚡ USB3503A-1-GL-TR | ⚙️ V24C5T50BL2 | D V300A15C500BG | ➡️ V375C48H150AK |
| ➡️ VE-J44-EZ | ⚙️ VI-810-165 | ⚡ VNP14N04-E | ⚙️ VS-10MQ060NPBF | ➡️ W9812G6JH-6I |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited