









	PI49FCT3807HEX	
	Manufacturer Part Number:	PI49FCT3807HEX
	Manufacturer/Brand:	Diodes Incorporated
	Part of Description:	IC CLK BUFFER 1:10 50MHZ 20SSOP
	RoHs Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
	Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.		

Specifications	
Part Number	PI49FCT3807HEX
Manufacturer	Diodes Incorporated
Description	IC CLK BUFFER 1:10 50MHZ 20SSOP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	49FCT
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	50MHz
Package / Case	20-SSOP (0.209", 5.30mm Width)
Supplier Device Package	20-SSOP
Number of Circuits	1
Voltage - Supply	3 V ~ 3.6 V
Output	CMOS, TTL
Input	CMOS, TTL
Ratio - Input:Output	1:10
Differential - Input:Output	No/No
Packaging	Tape & Reel (TR)

PI49FCT3807HEX is New Original in Stock, Search PI49FCT3807HEX Datasheets, PDF, Inventory at Y-IC.com Online, Order PI49FCT3807HEX Diodes Incorporated with warrantied and confidence. RFQ PI49FCT3807HEX : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>PI49FCT3807HC PI PI49FCT3807HC PI</p>	 <p>PI49FCT3807HCX PERICOM PI49FCT3807HCX PERICOM</p>	 <p>PI49FCT3807QC PERICOM PI49FCT3807QC PERICOM</p>	 <p>PI49FCT3807HEA PERICOM PERICOM SSOP20</p>
 <p>PI49FCT3807HX PERICOM PERICOM SOP</p>	 <p>PI49FCT3807HEC Pericom Semiconductor Corp. (Diodes Incorporated) PI49FCT3807HEC PERICOM</p>	 <p>PI49FCT3807Q PERICOM PI49FCT3807Q PERICOM</p>	 <p>PI49FCT3807QBX Pericom Semiconductor Corp. (Diodes Incorporated) PI49FCT3807QBX PERICOM</p>

Hot Parts More

- | | | | | |
|--------------------|---------------------|--------------------|------------------------|----------------------|
| 0402YA1R8CAT2A | 08055C472KAT2M | 12063A100FAT2A | D 12067C222KAT2A | 1812HC122KAT3A\SB |
| 1DI200A-020 | 2MBI200-060 | D ACPM-7833-TR1 | AP2301FGEG-7 | B39421R2528B110 |
| BAR43SNFILM-H/J | C1005C0G1H090C050BA | C1608JB1E154K080AA | C3216X7R1V475K085AC | CGA3E2X8R2A222K080AD |
| DM74AS280N | DS1267A1-010 | FOD2741CSD | FQPF90N08 | GRM1886P1H240JZ01D |
| GRM319R71A105MC01D | H5DU2562GTR-E3C | HCPL0530R2 | LBC807-40WT1G | LD1117ADJ-18TR |
| LFL215G37TC1A210 | LM3702XCBPX-308 | D LNBTVS3-220U | LQH3N8R2M04M00-01/T052 | M58WR032KB70ZB |
| MAX3748AETE-T | MT5561PUDT/B | NJU4066BM | NMA2405SC | PC357N3J000F |
| PMDXB950UPE | R250CH02C2H0 | S-13A1C15-E6T1U3 | S150MND8 | SA52844002 |
| SB5100-T | SC1302CIS | TCM320AC37CDW | TX1470NL | TYN808GRG |
| VE-J11-MW | WM1830ECSN005/R | WSR51L000FEA | XC61GN1202HR | ZTX749STOA |