


	<b>Manufacturer Part Number:</b> UJA1069TW24/3V3:51
	<b>Manufacturer/Brand:</b> NXP Semiconductors / Freescale
	<b>Part of Description:</b> IC LIN FAIL-SAFE 24-HTSSOP
	<b>Datasheets:</b>  <a href="#">UJA1069TW24/3V3:51.pdf</a>
<b>RoHS Status:</b>  Lead free / RoHS	<b>Stock Condition:</b> Compliant New original, Stock Available.
<b>Ship From:</b> Hong Kong	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	UJA1069TW24/3V3:51
Manufacturer	NXP Semiconductors / Freescale
Description	IC LIN FAIL-SAFE 24-HTSSOP
Category	Integrated Circuits (ICs) > Interface - Specialized
Part Status	Require For Quote & Check Stock
Series	-
Mounting Type	Surface Mount
Interface	LIN (Local Interconnect Network)
Applications	Automotive
Package / Case	24-TSSOP (0.173", 4.40mm Width) Exposed Pad
Supplier Device Package	24-HTSSOP
Voltage - Supply	3.3V
Packaging	Tape & Reel (TR)

UJA1069TW24/3V3:51 is New Original in Stock, Search UJA1069TW24/3V3:51 Datasheets, PDF, Inventory at Y-IC.com Online, Order UJA1069TW24/3V3:51 NXP Semiconductors / Freescale with warrantied and confidence. RFQ UJA1069TW24/3V3:51 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>UJA1069TW24/3V3,51</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 24-HTSSOP</p>	 <p><b>UJA1069TW24/5V0/C:</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 24HTSSOP</p>	 <p><b>UJA1075A50W</b> NXP UJA1075A50W NXP</p>	 <p><b>UJA1069TW24/3V0:51</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 24-HTSSOP</p>
 <p><b>UJA1069TW24/5V0,51</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 24-HTSSOP</p>	 <p><b>UJA1069TW/5V0/C/T,</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 32HTSSOP</p>	 <p><b>UJA1069TW24/5V0:51</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 24-HTSSOP</p>	 <p><b>UJA1069TW/5V0/C/T</b> NXP Semiconductors / Freescale IC LIN FAIL-SAFE 32HTSSOP</p>

### Hot Parts

More

- |                    |                        |                       |                       |                      |
|--------------------|------------------------|-----------------------|-----------------------|----------------------|
| ⊕ 12101U361JAT2A   | ↔ 18122C154JAT2A       | ⇒ 6MBI30FA-060        | D A45L-0001-0310      | ↔ ADP3207JCPZ        |
| ⊖ ADS1100A1IDBVR   | ⊕ APP003SN             | D APR3011-43AI-TRL    | ⇒ AT25FS040N-SH27DE-T | ↔ ATTINY48-12PU      |
| ⊕ BCR185S-E6327    | ⊖ BYW29FP-200          | ⊕ CSTCC4.00MGA184P-TC | ↔ DMP6185SK3          | ↔ FDMC86248          |
| D FS7SM-16A        | ⊕ GRM033R71A103KA01J   | ⊖ IDT72V3650L15PF     | ⊕ IRFD9210            | ↔ L88M05TL-TL-E      |
| ⇒ LQP03TN3N9B00D   | ↔ LQW15AN27NH00D       | ⊕ MG100Q2YS42         | ⊖ MMG75SR120B         | ↔ MX30UF1G18AC-TI    |
| ↔ N630FH30         | ⇒ NL17SZ86DFT2         | D PCA9554D            | ⊕ PL3500A25P          | ⊖ PS48M3V3CS         |
| ⊕ RL25FTR200F-0.2R | D RLF12545T-1R9N100-PF | ⇒ SBA500AA160         | ↔ SKHI22BH4R          | ↔ SMAJ8.0CA-E3/61    |
| ⊖ SN74ABT245BNSR   | ⊕ SN74HC4040APWR       | ↔ SOMC1603100RGEA     | ⇒ SP10-110S5          | ↔ SPX3940AT-L-3-3/TR |
| ⊕ ST180S12P2V      | ⊖ SY56011R             | ⊕ T378N04TOF          | D TLC5947RHBR         | ↔ TMC3003R2C50       |
| ↔ TPS650532RGER    | ⊕ V300B48T250A3        | ⊖ VD241212H-3W        | ⊕ WS1413-TR1G         | ↔ ZUW15-48-12        |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited