


	SL2305NZSC
	Manufacturer Part Number: SL2305NZSC
	Manufacturer/Brand: Energy Micro (Silicon Labs)
	Part of Description: IC BUFFER 140MHZ 5CH 3.3V 8SOIC
Datasheets:  SL2305NZSC.pdf	RoHS Status:  Lead free / RoHS
Stock Condition: Compliant New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	SL2305NZSC
Manufacturer	Energy Micro (Silicon Labs)
Description	IC BUFFER 140MHZ 5CH 3.3V 8SOIC
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Frequency - Max	140MHz
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Number of Circuits	1
Voltage - Supply	3 V ~ 3.6 V
Output	LVC MOS
Input	Clock
PLL	Yes
Ratio - Input:Output	1:5
Differential - Input:Output	No/No
Divider/Multiplier	No/No
Packaging	Tube

SL2305NZSC is New Original in Stock, Search SL2305NZSC Datasheets, PDF, Inventory at Y-IC.com Online, Order SL2305NZSC Energy Micro (Silicon Labs) with warrantied and confidence.
RFQ SL2305NZSC : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SL2305NZSIT Energy Micro (Silicon Labs) IC BUFFER 140MHZ 5CH 3.3V 8SOIC</p>	 <p>SL2304NZZI-12T Energy Micro (Silicon Labs) IC CLK BUFFER 1:4 140MHZ 8TSSOP</p>	 <p>SL2304NZZI-1 Energy Micro (Silicon Labs) IC CLK BUFFER 1:4 140MHZ 8TSSOP</p>	 <p>SL2305BC-1H SILICONLA SL2305BC-1H SILICONLA</p>
 <p>SL2304NZZI-1T Energy Micro (Silicon Labs) IC CLK BUFFER 1:4 140MHZ 8TSSOP</p>	 <p>SL2304NZZI-1Z Energy Micro (Silicon Labs) IC CLK BUFFER 1:4 140MHZ 8TSSOP</p>	 <p>SL2305SC-1H Energy Micro (Silicon Labs) IC BUFFER 140MHZ 5CH 3.3V 8SOIC</p>	 <p>SL2305NZSI Energy Micro (Silicon Labs) IC BUFFER 140MHZ 5CH 3.3V 8SOIC</p>

Hot Parts

More

- | | | | | |
|--------------------|-------------------|------------------------|-----------------------|--------------------------|
| ⊛ 12061A120GAT9A | ↔ 12106D107KAT9A | ⇒ ADG412BRZ-REEL | D ADV7528BCBZ-P | ↗ AKU2002BR |
| ⊣ AP2301GN | ⊛ BA17818FP-E2 | D BYW29E-150 | ⇒ C3216X5R2A474M160AA | ↗ CD4047BCM |
| ⊛ CM100DY-24N F | ⊣ D24050S5-3W | ⊛ D315CH35FOO | ↔ DS2153Q-A7+T&R | ↗ DSC1123CI12-100.00000T |
| D FDS8858CZ-NL | ⊛ FFP08H60STU | ⊣ FIAM2CN1 | ⊛ FTR-K2AK012T | ↗ HY12P10D |
| ⇒ HZU7.5B1TRF-EQ | ↔ ISD9160FIMS05 | ⊛ ISPLSI2032E-110LT48I | ⊣ LD051C103KAB4A | ↗ LPC47M997-NW |
| ↔ LQH32MNR68M01L | ⇒ LT1880CS5#PBF | D LTW-089ETCGN24 | ⊛ MAX428ACSA | ⊣ MC100EP101FAR2 |
| ⊛ MCP4021T-103E/SN | D MK3807-01RILFTR | ⇒ OPA330AIDR | ↔ PH50S48-5 | ↗ PKT4113P1 |
| ⊣ SCK3-100A | ⊛ SD25-0836R8UU33 | ↔ SKIIP32NAC063T42 | ⇒ SMAJ6.0CA-E3/61T | ↗ SMCJ18CA |
| ⊛ STP7NK80ZFP | ⊣ T160N08BOC | ⊛ T9GH121032DH | D TPS54428DDAR | ↗ TPS62291DRVR |
| ↔ UC3902DTRG4 | ⊛ WSL2512R0110FEA | ⊣ XC1900A-20SR | ⊛ XC2318TQ100C-5094 | ↗ ZXMN6A25KTC |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited