









	<h2 style="color: #e67e22;">MAX6865UK42D2S+T</h2>	
	<b>Manufacturer Part Number:</b>	MAX6865UK42D2S+T
	<b>Manufacturer/Brand:</b>	Maxim Integrated
	<b>Part of Description:</b>	IC MPU SUPERVISOR SOT23-5
	<b>Datasheets:</b>	<a href="#">1.MAX6865UK42D2S+T.pdf</a> <a href="#">2.MAX6865UK42D2S+T.pdf</a>
	<b>RoHs Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	

### Specifications

Part Number	MAX6865UK42D2S+T
Manufacturer	Maxim Integrated
Description	IC MPU SUPERVISOR SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	40 ms Minimum
Voltage - Threshold	4.2V
Packaging	Tape & Reel (TR)

MAX6865UK42D2S+T is New Original in Stock, Search MAX6865UK42D2S+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6865UK42D2S+T Maxim Integrated with warrantied and confidence. RFQ MAX6865UK42D2S+T : Info@Y-IC.com

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>MAX6865UK42D1S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK42D3L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK42D1L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK41D6S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>
 <p><b>MAX6865UK42D3S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK42D4L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK42D2L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK42D5L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>

### Hot Parts

More

04023U7R5DAT2A	06035C100KAT2A	A3916GESTR-T	ACNW3190-000E	AOT25S65
AZ1086T-3.3E1	C1005X6S1E683M050BC	C3225X5R2A225M230AB	CC0805JRX7R9BB182	CC1206JKNP09BN822
CS612216B	CX24153-44A	ETK4863VR	FS312F-G	FSA3357L8X
FSS101-TL-E	G6K-2G-Y-5V	GRM0335C1E330JA01D	GRM1557U1H6R2DZ01D	GRM188R70J224KA88D
HGT1S12N60C3	HR611031	IRDAK0705170	JMK316B7106KL-T	L-15WR33JV4E
LM5574MTX	MAX6390XS31D4+T	MC100ELT24DR2G	MC74LCX244DTEL	MC78PC18NTRG
ML4851CS-3	MX584KCSA	NJU7662M-TE3	PCI4450GJG	PMR290UNE
PT5108X23E-33	R2J20601NPEB	S-1323B33PF-N8STFG	SAFEA1G88KB7F00R15	SFH213FA
SI3905DV-T1-E3	SI4401DDY-T1-GE3	SUD25N04-25-T4-E3	TLC27L4BC	TT121N13KOF
UPD78F0034AGC-8BS	VI-PU00-CWW	VLP6045LT-220M	WM8781GEDS	ZS32405

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited