


 A Renesas Company	<b>ISL33001IRT2Z-T</b>
	<b>Manufacturer Part Number:</b> <a href="#">ISL33001IRT2Z-T</a>
	<b>Manufacturer/Brand:</b> <a href="#">Intersil</a>
	<b>Part of Description:</b> IC ACCELERATOR I2C HOTSWAP 8TDFN
	<b>Datasheets:</b>  <a href="#">ISL33001IRT2Z-T.pdf</a>
	<b>RoHS Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, Stock Available.
	<b>Ship From:</b> Hong Kong
Image may be representation. See specs for product details.	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









### Specifications

Part Number	<a href="#">ISL33001IRT2Z-T</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC ACCELERATOR I2C HOTSWAP 8TDFN
Category	<a href="#">Integrated Circuits (ICs) &gt; Interface - Signal Buffers,</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Current - Supply	4mA
Operating Temperature	-40°C ~ 85°C
Type	Buffer, Accelerator
Number of Channels	2
Applications	I <sup>2</sup> C - Hotswap
Package / Case	8-WDFN Exposed Pad
Supplier Device Package	8-TDFN (3x3)
Voltage - Supply	2.3 V ~ 5.5 V
Output	2-Wire Bus
Input	2-Wire Bus
Delay Time	-
Data Rate (Max)	-
Signal Conditioning	-
Capacitance - Input	10pF
Packaging	Tape & Reel (TR)

ISL33001IRT2Z-T is New Original in Stock, Search ISL33001IRT2Z-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL33001IRT2Z-T Intersil with warrantied and confidence. RFQ ISL33001IRT2Z-T : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <b>ISL3298EIRTZ-T</b> Intersil IC TX ESD RS485/422 LP 8-TDFN	 <b>ISL3298EFRTZ-T</b> Intersil IC TX ESD RS485/422 LP 8-TDFN	 <b>ISL33001IUZ-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8MSOP	 <b>ISL33001IRT2Z</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN
 <b>ISL33001MSOPEVAL1Z</b> Intersil EVAL BOARD ISL33001 8MSOP	 <b>ISL33001IRTZ-T</b> Intersil IC ACCELERATOR I2C HOTSWAP 8TDFN	 <b>ISL33001IBZ</b> Intersil IC ACCELERATOR I2C HOTSWAP 8SOIC	 <b>ISL33001IUZ</b> Intersil IC ACCELERATOR I2C HOTSWAP 8MSOP

### Hot Parts

[More](#)

- |  |  |   |   |   |
|--|--|---|---|---|
|  08052C682JAT2A     |  163CMQ080          |  5SNS0150V172100 |  AK4181AVT     |  ARA05050RS12P1  |
|  B39881-B4701-Z10   |  BAV99W-L-R1        |  BD3180FV        |  BD8918FV-E2   |  C0402C0G1C4R3B  |
|  CL21C102JBCNNL     |  CSTCC4M19G53-R0    |  CTT320GK16      |  EL4584CSZ     |  EVG31-050       |
|  FD800R33KL2C-K_B5  |  GRM1885C2A5R9DA01D |  HAT2103RJ       |  HD6433826A48W |  IMP708TESA-T    |
|  IRF610STRRPBF      |  ISO7320FCQDRQ1     |  IXTY44N10T      |  KBPC5012      |  LB3218T1R0M     |
|  LP5951MFX-3.3/NOPB |  LTC1430IS          |  MASWSS0005      |  MAX232ESE+T   |  MBRA240T3G      |
|  MCR18EZHJ362       |  MDS35-16           |  MIC811SUY       |  N450CH26      |  OB3613YCPA      |
|  P6KE16CA           |  PAH150S48-24       |  PI3B3861QEX     |  PMA15S24      |  S-8261CBS-I6T1U |
|  SKM40GAH123D       |  SP211BCA-L/TR      |  STS3DPFS30      |  STTA5012TV1   |  TPS64201DBVR    |
|  VS-50WQ10FNTRPBF   |  X9315UM-2.7T1      |  XC61CN2602NR    |  ZXMN2088DE6TA |  ZXTBM322TA      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited