









	<h2 style="color: red;">LB1923M-TLM-E</h2>
 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>Manufacturer Part Number:</b> LB1923M-TLM-E</p> <p><b>Manufacturer/Brand:</b> AMI Semiconductor / ON Semiconductor</p> <p><b>Part of Description:</b> IC MOTOR CTRLR PAR/PWM QIP44MA</p> <p><b>RoHs Status:</b>  Lead free / RoHS Compliant</p> <p><b>Stock Condition:</b> New original, 1048 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	LB1923M-TLM-E
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR CTRLR PAR/PWM QIP44MA
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	1048 pcs Stock
Series	-
Technology	-
Operating Temperature	-20°C ~ 80°C (TA)
Mounting Type	Surface Mount
Interface	Parallel
Applications	General Purpose
Package / Case	44-BQFP
Supplier Device Package	44-QIPM
Voltage - Supply	4.4 V ~ 7 V
Function	Controller - Commutation, Direction Management
Current - Output	-
Output Configuration	Half Bridge (3)
Voltage - Load	-
Motor Type - Stepper	-
Motor Type - AC, DC	Brushless DC (BLDC)
Step Resolution	-
Packaging	Tape & Reel (TR)

LB1923M-TLM-E is New Original in Stock, Search LB1923M-TLM-E Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1923M-TLM-E AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1923M-TLM-E : Info@Y-IC.com

### You May Be Also Be interested In:

 <p><b>LB1927-E</b> AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR/PWM 30DIP</p>	 <p><b>LB1928</b> SANYO LB1928 SANYO</p>	 <p><b>LB1927</b> SANYO LB1927 SANYO</p>	 <p><b>LB1923M-TE-L</b> SANYO LB1923M-TE-L SANYO</p>
 <p><b>LB1924A-E</b> SANYO/PBF LB1924A-E SANYO/PBF</p>	 <p><b>LB1922</b> SANYO LB1922 SANYO</p>	 <p><b>LB1924</b> SANYO LB1924 SANYO</p>	 <p><b>LB1921-E</b> SONY LB1921-E SONY</p>

### Hot Parts

More

⊗ LB1861M-TLM-E	↔ LB1861M-TLM-H	⇒ LB1862M-NMB-TLM3-E	D LB1862M-TE-L	⇒ LB1862M-TLM-E
⊣ LB1862M-TLM-H	⊗ LB1862MC-AH	D LB1863M-DELTA-TLM-H	⇒ LB1863M-TE-L	⇒ LB1863M-TLM-H
⊗ LB1867M-MPB-H	⊣ LB1867M-TLM-E	⊗ LB1868M-NMB-TLM3-E	↔ LB1868M-TE-L	⇒ LB1868M-TLM-E
D LB1868M-TLM-H	⊗ LB1869M-TLM-E	⊣ LB1870M-TE-L	⊗ LB1877V-MPB-E	⇒ LB1877V-TLM
⇒ LB1879M-TE-L	↔ LB1906CL-TLM	⊗ LB1906CL-TLM-E	⊣ LB1921-E	⇒ LB1923M-TE-L
↔ LB1924A-E	⇒ LB1930M-TLM	D LB1930M-TLM-E	⊗ LB1930MC-AH	⊣ LB1933M-MPB-E
⊗ LB1934T-MPB-E	D LB1935CL-TLM-E	⇒ LB1935FA-AH	↔ LB1935T-TLM-E	⇒ LB1936V-MPB-E
⊣ LB1936V-TLM	⊗ LB1936V-TLM-E	↔ LB1937T-MPB-E	⇒ LB1938FA-AH	⇒ LB1938T-TLM
⊗ LB1938T-TLM-E	⊣ LB1939T-MPB-E	⊗ LB1939T-TLM-E	D LB1940U-TLM-E	⇒ LB1941T-TLM
↔ LB1941T-TLM-E	⊗ LB1945H-TLM-E	⊣ LB1946-E	⊗ LB1947-E	⇒ LB1950V-TLM

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited