
	<p>X40021S14-BT1</p>
	<p>Manufacturer Part Number: X40021S14-BT1</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC VOLTAGE MONITOR DUAL 14-SOIC</p> <p>Datasheets:  X40021S14-BT1.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X40021S14-BT1
Manufacturer	Intersil
Description	IC VOLTAGE MONITOR DUAL 14-SOIC
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-SOIC (0.154", 3.90mm Width)
Supplier Device Package	14-SOIC
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	2
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	2.6V, 4.6V
Packaging	Tape & Reel (TR)

X40021S14-BT1 is New Original in Stock, Search X40021S14-BT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40021S14-BT1 Intersil with warrantied and confidence. RFQ X40021S14-BT1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40020V14I-CT1 Intersil IC VOLTAGE MONITOR DUAL 14-TSSOP</p>	 <p>X40021S14I-AT1 Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>	 <p>X40021S14-A Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>	 <p>X40021S14-AT1 Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>
 <p>X40021S14-CT1 Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>	 <p>X40021S14-C Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>	 <p>X40021S14I-B Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>	 <p>X40021S14I-A Intersil IC VOLTAGE MONITOR DUAL 14-SOIC</p>

Hot Parts

[More](#)

- | | | | | |
|--|--|--|---|---|
|  12065A911FAT2A |  1812AC471MAT1A\SB |  215-0692006-00 |  5STP04D5200 |  70HFLR60S05 |
|  7MBR30SA060 |  AB8500-LB1TOHOO |  AP73333-12SAG-7 |  BA3822FS |  CBK-2415SF |
|  CGA5K4X7R2J153K130AA |  CGJ5F2C0G2A472J085AA |  CL21B475KOFNNNE |  CL31C332JBFNNNF |  CM8561GISTR |
|  DCX69-16-13 |  DFC10E12S15 |  DMC3021LSDQ |  EPM3064ATC100-10N |  FARM2C12 |
|  GRM0225C1E9R0CA03L |  GRM1555C1H7R1WZ01D |  HD6433660D73FYV |  HM514256AZP-8 |  HMC684LP4ETR |
|  IXTH90P10P |  LT3055IDE#PBF |  LTC4150CMS#TRPBF |  MAX4618CPE |  MC100EPT24DR2G |
|  MM8030-2610 |  MMBZ5239B-7-F |  MR852RLG |  NJU6333QE |  OB431AEP |
|  P4SMA110A |  PIC16LF1614-I/SL |  RC2512JK-07-24K |  SL38160CZC-25AH |  SM8S22HE3/2D |
|  SN74LVTH373PWR |  SPT7861SCS |  SY88149CLKGTR |  TLC25M4BCN |  TPCA8040-H |
|  TPS2363PFBR |  UPD78053GC-263-3B9 |  V110C12T100BG |  XC3S1400AN-4FG676C |  XC95288XL-7FG256C |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited