









 <p>A Renesas Company</p>	<p><b>ISL9008IECZ-T</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL9008IECZ-T</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC REG LDO 1.8V 0.15A SC70-5</p> <p><b>Datasheets:</b> <a href="#">ISL9008IECZ-T.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, 32000 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	ISL9008IECZ-T
Manufacturer	Intersil
Description	IC REG LDO 1.8V 0.15A SC70-5
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	32000 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Voltage - Input	2.3 V ~ 6.5 V
Package / Case	5-TSSOP, SC-70-5, SOT-353
Supplier Device Package	SC-70-5
Voltage - Output	1.8V
Current - Output	150mA
Regulator Topology	Positive Fixed
Voltage - Dropout (Typical)	-
Number of Regulators	1
Current - Limit (Min)	175mA
Packaging	Tape & Reel (TR)

ISL9008IECZ-T is New Original in Stock, Search ISL9008IECZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL9008IECZ-T Intersil with warrantied and confidence. RFQ  
ISL9008IECZ-T : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>ISL9008IEHZ-T</b> Intersil IC REG LDO 2.75V 0.15A SC70-5</p>	 <p><b>ISL9008AIRUKZ-T</b> Intersil IC REG LDO 2.85V 0.15A 6UTDFN</p>	 <p><b>ISL9008AIRUMZ-T</b> Intersil IC REG LDO 3V 0.15A 6UTDFN</p>	 <p><b>ISL9008IEKZ-T</b> Intersil IC REG LDO 2.85V 0.15A SC70-5</p>
 <p><b>ISL9008IEMZ-T</b> Intersil IC REG LDO 3V 0.15A SC70-5</p>	 <p><b>ISL9008IEFZ-T</b> Intersil IC REG LDO 2.5V 0.15A SC70-5</p>	 <p><b>ISL9008AIRUNZ-T</b> Intersil IC REG LDO 3.3V 0.15A 6UTDFN</p>	 <p><b>ISL9008IEJZ-T</b> Intersil IC REG LDO 2.8V 0.15A SC70-5</p>

### Hot Parts

[More](#)

⊕ 08051A680JAT4A	↔ 2MBI200SK-060	⇒ 7MBR25VW120-50	D ACST10-7ST	⇒ ADM211ARZ
⊕ B82494A1103K	⊕ BZD27C7V5P-E3-08	D CC0805JRNPOBBN100	⇒ CY8CTMG200A-32LQXI	⇒ DLP1NDN670HL4L
⊕ E52HA0.75C-A-W	⊕ ELM7540NBB-S	⊕ F921D224MPA	↔ FF400R12KE3	⇒ FQD6N50CTF
D HC-TS186V4UP12	⊕ HK100547NJ-T	⊕ IXFN100N10S3	⊕ JW100A1-49	⇒ LIS2DETR
⇒ LP2985A-28DBVR	↔ LT4356CMS-3#PBF	⊕ LTC1874EGN#TR	⊕ MAX6338KUB	⇒ MAX8890ETCBBB
↔ MB83256M	⇒ MB95128MBPMC-GS-120E2	D MC7808CD2TR4G	⊕ MK5811STR	⊕ MM74HCT273WMX
⊕ N3476TC400	D P4KE18A-E3/54	⇒ PAM3106DAB120	↔ PESD3V3Z1BZF	⇒ QCPL-314H
⊕ R4050570	⊕ SDQ12-100-R	↔ SFH4059-AW	⇒ SI4200-GM	⇒ SKKH105/14E
⊕ SP809EK-L-3.1/TR	⊕ STTH12002TV	⊕ TESVSP0J155M8R	D TMP87EP26F-1J15	⇒ TPS7A7100RGTR
↔ UCC381DP-5	⊕ UPA2757GR-E1	⊕ V300C12M150BL	⊕ VI-J73-IX	⇒ VT202BX-ADJ

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited