


 <p>A Renesas Company</p>	<p><b>ISL88013IH544Z-T7A</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL88013IH544Z-T7A</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC VOLT MONITR WATCHDOG SOT23-5</p> <p><b>Datasheets:</b>  <a href="#">ISL88013IH544Z-T7A.pdf</a></p> <p><b>RoHs Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









### Specifications

Part Number	<a href="#">ISL88013IH544Z-T7A</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC VOLT MONITR WATCHDOG SOT23-5
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Open Drain, Push-Pull
Reset	Active High/Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	4.38V
Packaging	Original-Reel®

ISL88013IH544Z-T7A is New Original in Stock, Search ISL88013IH544Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88013IH544Z-T7A Intersil with warrantied and confidence. RFQ ISL88013IH544Z-T7A : [Info@Y-IC.com](mailto:Info@Y-IC.com)







### You May Be Also Be interested

In:

 <p><b>ISL88013IH529Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5</p>	 <p><b>ISL88013IH529Z-T7A</b> Intersil IC VOLT MONITR WATCHDOG SOT23-5</p>	 <p><b>ISL88014EVAL1Z</b> Intersil EVALUATION BOARD FOR ISL88014</p>	 <p><b>ISL88013IH531Z</b> INTERMIL ISL88013IH531Z INTERMIL</p>
 <p><b>ISL88013IH544Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5</p>	 <p><b>ISL88013IH531Z-TK</b> Intersil IC VOLTAGE MONITOR DUAL SOT23-5</p>	 <p><b>ISL88013IH531Z-T7A</b> Intersil IC VOLT MONITR WATCHDOG SOT23-5</p>	 <p><b>ISL88014IH5Z-T7A</b> Intersil IC VOLT MONITR WATCHDOG SOT23-5</p>

### Hot Parts

[More](#)

- |   |   |  |  |   |
|---|---|--|--|---|
|  0201YA100JAQ2A        |  06033A910GAT2A        |  06035A5R6B4T2A       |  D 0805YC184JAT2A      |  112MT160KPBF          |
|  1808WC102KAT1A        |  AA104-73              |  D AC0402KRX7R9BB682  |  => ADF7901B           |  => AP2402A31KTR-E1    |
|  APL5151-33BI-TRL      |  1- ATA2501DB-40N      |  0 C3225JB0J107MT000N |  => CF4558CB           |  => CL32A226MOJNNNE    |
|  D DS2401X1-S#T        |  0 DS90LV031ATM        |  1- FOD3184SV         |  0 GCM0335C1E2R3CD03D  |  => GQM2195C2E330JB12D |
|  => GRM0225C1E6R5CA03L |  => GRM0337U1H1R5CD01D |  0 GRM1555C2A7R3DA01D |  1- GRM1885C1H331JA01J |  => GRM31A5C3A181JW01D |
|  => H1200NC200         |  => HT-121BP5          |  D HZD300F-48S24      |  0 IR2015SPBF          |  1- IRFH7446TRPBF.     |
|  0 IRU1117-18CSTRPBF.  |  D KQ0805TTER10K       |  => LM2574M-5.0       |  => MAX706REPA         |  => MC33298DWR2        |
|  1- MC74VXC16240DTR2   |  0 MMO75-16I01         |  => P2500SBL          |  => SAFE836MFL0F00R14  |  => SAH-XC2336B-40F80L |
|  0 SE2571U-R           |  1- SI3446ADV-T1-GE3   |  0 SKN20/02UNF        |  D SS2PH9HE3/84A       |  => SSM5H07TU          |
|  => TDB2HKF85N18KOF    |  0 TPCC8061-H          |  1- UMD12.N.TR        |  0 UQCFVA201JAT2A\500  |  => V24B24H200AL       |

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited