

	<p>SY89544UMI</p>
	<p>Manufacturer Part Number: SY89544UMI</p>
	<p>Manufacturer/Brand: Micrel / Microchip Technology</p>
	<p>Part of Description: IC MUX 4:1 LVDS DIFF 2.5V 32MLF</p>
<p>Image may be representation. See specs for product details.</p>	<p>Datasheets:  SY89544UMI.pdf</p>
	<p>RoHs Status: Contains lead / RoHS non-compliant</p>
	<p>Stock Condition: New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	SY89544UMI
Manufacturer	Micrel / Microchip Technology
Description	IC MUX 4:1 LVDS DIFF 2.5V 32MLF
Category	Integrated Circuits (ICs) > Logic - Signal Switches,
Part Status	Require For Quote & Check Stock
Series	Precision Edge®
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Multiplexer
Package / Case	32-VFQFN Exposed Pad, 32-MLF®
Supplier Device Package	32-MLF® (5x5)
Voltage - Supply	2.375 V ~ 2.625 V
Circuit	1 x 4:1
Voltage Supply Source	Single Supply
Current - Output High, Low	-
Independent Circuits	1
Packaging	Tube

SY89544UMI is New Original in Stock, Search SY89544UMI Datasheets, PDF, Inventory at Y-IC.com Online, Order SY89544UMI Micrel / Microchip Technology with warrantied and confidence. RFQ SY89544UMI : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SY89545LMI-TR Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 3.3V 32-MLF</p>	 <p>SY89544UMI-TR Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 2.5V 32-MLF</p>	 <p>SY89545LMI Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 3.3V 32MLF</p>	 <p>SY89543LMG-TR Micrel / Microchip Technology IC MUX 2:1 LVDS DUAL 3.3V 32-MLF</p>
 <p>SY89545LMG-TR Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 3.3V 32-MLF</p>	 <p>SY89544UMG Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 2.5V 32MLF</p>	 <p>SY89545LMG Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 3.3V 32MLF</p>	 <p>SY89544UMG-TR Micrel / Microchip Technology IC MUX 4:1 LVDS DIFF 2.5V 32-MLF</p>

Hot Parts

More

- | | | | | |
|---------------------|-------------------------|------------------|------------------|---------------------|
| 06032U3R3BAT2A | 18121A222JAT2A | 1DI400MN-120-02 | D 2220GC562KAT1A | 7MBR35VP120-50 |
| AD8221BRZ | ADP3335ARMZ-3.3 | D BLM21GP220SN1D | BSC046N02KS | C1005X7R1H102M050BE |
| C3216C0G2W682J115AA | CL21A225KAFNNG | DS1085L25 | EMD07N50A | ESDA18-1F2 |
| FAN5355UC03X | GRM188R61H225KE11J | HCNW2601 | LM4030CMF-4.096 | LMSZ5237BT1G |
| LQH43CN151K03L | LT1086IT-5#PBF | M74HC132RM13TR | MAX632ACSA | MAX6348XR40-T |
| NJM2729E | NMC1206X5R106M6.3TRPLPF | NP40N055MLE | NUP4105MUTAG | P0603BDG |
| P588C6103 | P6KE36A-E3/73 | PMCXB900UEZ | PSB162-16 | RN1425TE85 |
| S-24C16CI-J8T1U3 | S-80851CNMC-B9C-T2 | S10MG-E3/I | SI2377DS-T1-GE3 | SRM20100LMT-10 |
| T221N18EOC | TD105N12KOF | TPS73131DBVR | TRS3232EQPW | UC2845AN |
| UJA1076ATW/3V3/WD | UMK063CG390JTHF | V28A5M175BL | V300A2C160A3 | VI-2W1-CX-B1 |