


 A Renesas Company	ISL31470EIBZ-T7A
	Manufacturer Part Number: ISL31470EIBZ-T7A
	Manufacturer/Brand: Intersil
	Part of Description: IC TXRX RS485 FAULT PROT 14SOIC
	Datasheets:  ISL31470EIBZ-T7A.pdf
	RoHS Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL31470EIBZ-T7A
Manufacturer	Intersil
Description	IC TXRX RS485 FAULT PROT 14SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	14-SOIC (0.154", 3.90mm Width)
Supplier Device Package	14-SOIC
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Full
Receiver Hysteresis	25mV
Data Rate	250kbps
Packaging	Original-Reel®

ISL31470EIBZ-T7A is New Original in Stock, Search ISL31470EIBZ-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL31470EIBZ-T7A Intersil with warrantied and confidence.
RFQ ISL31470EIBZ-T7A : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL31470EIBZ-T Intersil IC TXRX RS485 FAULT PROT 14SOIC	 ISL3140AMZ INTERSIL ISL3140AMZ INTERSIL	 ISL3140MZ INTERSIL ISL3140MZ INTERSIL	 ISL31472EIBZ-T Intersil IC TXRX RS485 FAULT PROT 8SOIC
 ISL31472EIPZ Intersil IC TXRX RS485 FAULT PROT 8DIP	 ISL31472EIBZ Intersil IC TXRX RS485 FAULT PROT 8SOIC	 ISL31274EFBZ Intersil ISL31274EFBZ INTERSIL	 ISL31472EIBZ-T7A Intersil IC TXRX RS485 FAULT PROT 8SOIC

Hot Parts

More

- | | | | | |
|----------------------|----------------------|--------------------|--------------------|----------------------|
| ⊛ 0201ZG222ZAT2A | ↔ 12061A181JAT4A | ⇒ 12061A471FAT4A | D 12101C683KAT2P | ⇒ 12105C225K4Z2A |
| ⊣ 2225HA471KAT1A | ⊛ 2R6D15A-050AJY | D 461144280 | ⇒ ADM660ARZ-REEL | ⇒ AM27C010-300/BXA |
| ⊛ AP3606FNTR | ⊣ AS1100WE | ⊛ AS1129M3-3-3 | ↔ AS204-80 | ⇒ BU33TD3WG-GTR |
| D C2520C-39NJ | ⊛ CL21B102KECSFNC | ⊣ CL416AJE | ⊛ CNX36U300W | ⇒ CTZ3S-10B-X1-PF |
| ⇒ DMP2165UW | ↔ FDMS3606AS | ⊛ FJC2383YTF | ⊣ FOD2200T | ⇒ GRM1555C1E200GA01D |
| ↔ GRM3195C1H152JA01D | ⇒ GRM3195C1H203JA01D | D HTY37.5-P | ⊛ ICS9112M-06 | ⊣ LT1936EMS8E#PBF |
| ⊛ MAX3387ECUG+T | D MCP102T-195I/LB | ⇒ MIC803-44D2VM3TR | ↔ MMPQ2222A | ⇒ NCV8403STT1G |
| ⊣ NFM21PC104R1E3 | ⊛ PAH350S48-28/T | ↔ PE-68896NLST | ⇒ REF3325AIDCKRG4 | ⇒ S-1206B29-M3T1G |
| ⊛ SC8800GS2-381G | ⊣ SRF0905-400Y | ⊛ SW04CXC565 | D T599F13TEC | ⇒ T909N35TOF |
| ↔ TT95N600KOC | ⊛ USB3750A-1-A4-TR | ⊣ VI-710589 | ⊛ VLS252012CX-220M | ⇒ Z0109MN0 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited