









 <p>A Renesas Company</p>	<p><b>X40421V14-CT1</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">X40421V14-CT1</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC VOLT MON DUAL SUP/SW 14-TSSOP</p> <p><b>Datasheets:</b> <a href="#">X40421V14-CT1.pdf</a></p> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <p><b>Stock Condition:</b> New original, 31 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	<a href="#">X40421V14-CT1</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC VOLT MON DUAL SUP/SW 14-TSSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	31 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	2
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.6V, 2.9V
Packaging	Tape & Reel (TR)

X40421V14-CT1 is New Original in Stock, Search X40421V14-CT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40421V14-CT1 Intersil with warrantied and confidence. RFQ X40421V14-CT1 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>X40421V14I-A</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14-B</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14I-B</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14I-BT1</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>
 <p><b>X40421V14I-C</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14-BT1</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14I-AT1</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p><b>X40421V14-AT1</b> Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>

### Hot Parts

[More](#)

<a href="#">08055A271KAT2A</a>	<a href="#">12065E184MAT2A</a>	<a href="#">20TQ045STRR</a>	<a href="#">D 6DI30Z-050</a>	<a href="#">AD5040BRJZ</a>
<a href="#">AD7892AR-2</a>	<a href="#">ADR291FRZ</a>	<a href="#">D AN983B-BG</a>	<a href="#">AP1661P-E1</a>	<a href="#">AP5101SG-13</a>
<a href="#">ATMEGA128A-AU</a>	<a href="#">BUK6207-55C</a>	<a href="#">C0603C0G1E4R7B</a>	<a href="#">C2012X7R1H103K</a>	<a href="#">CD411660</a>
<a href="#">D CGA5L3X8R2A334M160AE</a>	<a href="#">CL31A106KACLNNC</a>	<a href="#">CM150RXL-34SA</a>	<a href="#">CM6800AGIP</a>	<a href="#">DAP202CT116</a>
<a href="#">DM54LS92J</a>	<a href="#">DV889B-3900-40</a>	<a href="#">ES1D-E3/61T</a>	<a href="#">ES1MTR-13</a>	<a href="#">FDP6035AL</a>
<a href="#">FFB20UP20DN_F085</a>	<a href="#">GP2W0004YP</a>	<a href="#">D GRJ188C70J475KE11D</a>	<a href="#">IS31FL3236-QFLS2-TR</a>	<a href="#">ISL58966CRZ-T13</a>
<a href="#">J2S-Q01A-F</a>	<a href="#">D LP3204B-ADB5F</a>	<a href="#">LQH32MN220K21L</a>	<a href="#">MAX5048BAUT+T</a>	<a href="#">MAX745EAP+T</a>
<a href="#">PDZ13B/DG</a>	<a href="#">PTS25-24-5</a>	<a href="#">RT9161-33CX</a>	<a href="#">S1206H3-TR</a>	<a href="#">SBR10E45P5-13</a>
<a href="#">SM02CXC220</a>	<a href="#">SN65LVCP22PWR</a>	<a href="#">SST39VF512-70-4C</a>	<a href="#">D STI4N62K3</a>	<a href="#">SX1509BIULTRT</a>
<a href="#">TD36N14LOF</a>	<a href="#">TD56N16KOF</a>	<a href="#">TK11547MTL</a>	<a href="#">V48C12C150A</a>	<a href="#">VI-B60-EU</a>

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited