

	<p>TSA5060AT/C1,518</p>
	<p>Manufacturer Part Number: TSA5060AT/C1,518</p>
	<p>Manufacturer/Brand: NXP Semiconductors / Freescale</p>
	<p>Part of Description: IC SYNTH FREQ 1.3GHZ 16-SOIC</p>
	<p>Datasheets:  TSA5060AT/C1,518.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	TSA5060AT/C1,518
Manufacturer	NXP Semiconductors / Freescale
Description	IC SYNTH FREQ 1.3GHZ 16-SOIC
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-20°C ~ 85°C
Mounting Type	Surface Mount
Type	PLL Frequency Synthesizer
Frequency - Max	1.3GHz
Package / Case	16-SOIC (0.154", 3.90mm Width)
Supplier Device Package	16-SO
Number of Circuits	1
Voltage - Supply	4.5 V ~ 5.5 V
Output	Clock, Crystal
Input	Clock, Crystal
PLL	No
Ratio - Input:Output	3:2
Differential - Input:Output	No/No
Divider/Multiplier	Yes/No
Packaging	Tape & Reel (TR)

TSA5060AT/C1,518 is New Original in Stock, Search TSA5060AT/C1,518 Datasheets, PDF, Inventory at Y-IC.com Online, Order TSA5060AT/C1,518 NXP Semiconductors / Freescale with warrantied and confidence. RFQ TSA5060AT/C1,518 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>TSA5060ATS PHILIPS TSA5060ATS PHILIPS</p>	 <p>TSA5060AT/C1 PHI TSA5060AT/C1 PHI</p>	 <p>TSA5155T PHI TSA5155T PHI</p>	 <p>TSA5060ATS/C1,118 NXP Semiconductors / Freescale IC SYNTH FREQ 1.3GHZ 16-SSOP</p>
 <p>TSA5076PFC TI TSA5076PFC TI</p>	 <p>TSA5060ATS/C1 PHI TSA5060ATS/C1 PHI</p>	 <p>TSA5059TS/C1 PHILTPS TSA5059TS/C1 PHILTPS</p>	 <p>TSA5059TS NXP TSA5059TS NXP</p>

Hot Parts

More

- | | | | | |
|-------------------------|-----------------------|----------------------|-------------------|--------------------|
| ⊗ 06033A320FAT4A | ↔ 1808HC102MAT9A | ⇒ 6DI85A-060/ | D 7MBP150RA060-55 | ↔ ACT6358NH-T |
| ⊣ AP1086D50G-13 | ⊗ BC413159B10-IPK-E4 | D BC41B143A06 | ⇒ BD62222HFP-TR | ↔ BYV44-500 |
| ⊗ C0402C0G1C080C | ⊣ C3216C0G1H153J/1.15 | ⊗ CDRH73NP-3R3NC | ↔ CL21B104KCFNNE | ↔ CPH6071-TL |
| D DDZ12BSF-7 | ⊗ DT18N14LOF | ⊣ GRM0225C1C150JD05D | ⊗ HFA08SD60STR | ↔ IRDAK0705169 |
| ⇒ IRGBC30M | ↔ IXGH32N60CD1 | ⊗ KXTE9-1050 | ⊣ LMBZ5231BLT1G | ↔ LT1017CS8#PBF |
| ↔ LTC2900-1IMS#PBF | ⇒ LTC4156IUFD#PBF | D LX5586HLL-TR | ⊗ MUBW15-12E7 | ⊣ N018RH12 |
| ⊗ PC3SD21NWZC | D PD301-M0139A | ⇒ PHK12NQ03LT | ↔ PP25-24-12 | ↔ SEN012DG-TL |
| ⊣ SI9183DT-50-T1-E3 | ⊗ SKKT106B14E | ↔ SKKT210/20E | ⇒ SMUN5113T1G | ↔ SSL2101T |
| ⊗ SST49LF004B-33-4C-NHE | ⊣ STM6778TGWB6F | ⊗ SUD50N06-16 | D T879N800TOF | ↔ TC54VN4602ECB713 |
| ↔ TC75S558F | ⊗ UPC2748TB-E3 | ⊣ UPD720112GK-9EU | ⊗ XC62KN5002PR | ↔ ZMV832BTA |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited