

	<h2 style="color: red;">LB1950V-TLM-E</h2>
	<p>Manufacturer Part Number: LB1950V-TLM-E</p> <p>Manufacturer/Brand: AMI Semiconductor / ON Semiconductor</p> <p>Part of Description: IC MOTOR DRIVER 3PH SL 30SSOP</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: ^{Compliant} New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	
















Specifications

Part Number	LB1950V-TLM-E
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER 3PH SL 30SSOP
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	*
Mounting Type	Surface Mount
Package / Case	30-LSSOP (0.220", 5.60mm Width)
Supplier Device Package	30-SSOP
Packaging	Tape & Reel (TR)

LB1950V-TLM-E is New Original in Stock, Search LB1950V-TLM-E Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1950V-TLM-E AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1950V-TLM-E : Info@Y-IC.com

You May Be Also Be interested

In:

 Not Actual Photo YIC International Co., Limited.  LB1960M-TLM SANYO LB1960M-TLM SANYO	 Not Actual Photo YIC International Co., Limited.  LB194S SANYO SANYO HSOP	 Not Actual Photo YIC International Co., Limited.  LB1951V-TRM SANYO LB1951V-TRM SANYO	 Not Actual Photo YIC International Co., Limited.  LB1951V SANYO LB1951V SANYO
 Not Actual Photo YIC International Co., Limited.  LB1960 SANYO LB1960 SANYO	 LB1950V-MPB-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER 3PH SL 30SSOP	 Not Actual Photo YIC International Co., Limited.  LB1950V-TLM SANYO LB1950V-TLM SANYO	 Not Actual Photo YIC International Co., Limited.  LB1951 SANYO LB1951 SANYO

Hot Parts

More

- | | | | | |
|----------------------|---------------------|--------------------|------------------|---------------------|
| ⊕ 08051AR82CAT2A | ↔ 12105C392MAT2M | ⇒ AD604ARZ | D AM4835EP-T1-PF | ⇒ AP7344D-2828RH4-7 |
| ⊖ BAV21W-7 | ⊕ BYG10K-E3/TR | D DRV8800PWPR | ⇒ F1205S-3W | ⇒ FQB33N10L |
| ⊕ GCM2165C1H202JA16D | ⊖ HCPL-M601 | ⊕ HCPL0452R2 | ↔ ICS1893BFT | ⇒ IXFH22N60P |
| D LDS3985PU15R | ⊕ LM56CIMMX/NOPB | ⊖ LM80CIMTX-5/NOPB | ⊕ MAX6025BEUR | ⇒ MAX6301ESA+ |
| ⇒ MAZ8068UML | ↔ MT47H64M8CF-25E:G | ⊕ N195CH12 | ⊖ NDC7001C | ⇒ NT6TL128M32BQ-G1 |
| ↔ PC924L0NSZ0F | ⇒ PIC12F615T-IJ/MF | D PS9303L-V-E3-A | ⊕ PT2312-S | ⊖ RAC104D-393J-39K |
| ⊕ S29PL032J60BFI123A | D SCM1250M | ⇒ SI5853CDC-T1-E3 | ↔ SI7483ADP | ⇒ SM04CXC220 |
| ⊖ SMBT1184LT1 | ⊕ SPB04N50C3 | ↔ SW42CXC15C | ⇒ TA20141603DH | ⇒ TC6501P120VCTTR |
| ⊕ TCA1C106M8R | ⊖ TEPSLA1C335M8R | ⊕ TF202-E4-TL-E | D TPS9126PWR | ⇒ VJ1210Y473KXBAT |
| ↔ VMO60-05F | ⊕ W4092ZC420 | ⊖ XC6202P902FR | ⊕ XWD4805-05CS1 | ⇒ ZXMN10A25K |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited