










 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">X93256UV14IZ-2.7</h2>		
	<p><b>Manufacturer Part Number:</b> <a href="#">X93256UV14IZ-2.7</a></p>		
	<p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p>		
	<p><b>Part of Description:</b> IC XDCP DUAL 32TAP 50K 14-TSSOP</p>		
	<p><b>Datasheets:</b>  <a href="#">X93256UV14IZ-2.7.pdf</a></p>		
	<p><b>RoHS Status:</b>  Lead free / RoHS</p>		
	<p><b>Stock Condition:</b> Compliant New original, Stock Available.</p>		
	<p><b>Ship From:</b> Hong Kong</p>		
<p>Image may be representation. See specs for product details.</p>	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>		

### Specifications

Part Number	<a href="#">X93256UV14IZ-2.7</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC XDCP DUAL 32TAP 50K 14-TSSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; Data Acquisition - Digital</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	XDCP™
Operating Temperature	-40°C ~ 85°C
Features	-
Interface	Up/Down (U/D, INC, CS)
Configuration	Potentiometer
Tolerance	±25%
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Number of Circuits	2
Voltage - Supply	2.7 V ~ 5.5 V
Memory Type	Non-Volatile
Resistance (Ohms)	50k
Taper	Linear
Number of Taps	32
Temperature Coefficient (Typ)	±35 ppm/°C
Resistance - Wiper (Ohms) (Typ)	1100 (Max)
Packaging	Tube


X93256UV14IZ-2.7 is New Original in Stock, Search X93256UV14IZ-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X93256UV14IZ-2.7 Intersil with warrantied and confidence.  
RFQ X93256UV14IZ-2.7 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>X93256WV14IZ-2.7</b> Intersil IC XDCP DUAL 32TAP 12.5K 14TSSOP</p>	 <p><b>X93255UV14IT1</b> Intersil IC XDCP DUAL 32-TAP 50K 14-TSSOP</p>	 <p><b>X93256WV14IZ-2.7T1</b> Intersil IC XDCP DUAL 32TAP 12.5K 14TSSOP</p>	 <p><b>X93255UV14I</b> Intersil IC DCP DUAL 50K 32TAP 14-TSSOP</p>
 <p><b>X93256UV14IZ-2.7T1</b> Intersil IC XDCP DUAL 32TAP 50K 14-TSSOP</p>	 <p><b>X93256WV14I-2.7T1</b> Intersil IC XDCP DUAL 32TAP 12.5K 14TSSOP</p>	 <p><b>X93254UV14I-3</b> Intersil IC DCP DUAL 50K 32TAP 14-TSSOP</p>	 <p><b>X93256UV14I-2.7T1</b> Intersil IC XDCP DUAL 32-TAP 50K 14-TSSOP</p>

### Hot Parts

[More](#)

 0402YG123ZAT2A	 08055A880FAT2A	 1206YD225MAT4A	 ADP160AUJZ-1.5-R7	 ADS5102IPFB
 AT45DB041D-SU-2.5	 ATTINY84A-MMHR	 BD9854MUV-E2	 BU4230G-TR	 C2520C-R12J
 CGA5L2X7R2A104K160AA	 CL-201HR-C	 CM100TJA-24F	 DS92LV010ATMX/NOPB	 DT180F10KEC
 ELM9822BB-S	 GRM2196P2A5R7DD01D	 HXB15H4G160CF-13K	 IP-262-CU-TR1	 IR2521DSTRPBF
 IR3841WMTR1PBF	 IRF1010EZ	 IRKE91-12	 IRKH26/16	 ISL8501IRZ-T
 KP216K1409	 LAE675-U2-2-3A-50	 LM2750LDX-5.0/NOPB	 LMV716MMX	 LP38501TJ-ADJ/NOPB
 LS204IDT	 LT1072CS8#TRPBF	 LT1490AIS8	 LTC1662IMS8#PBF	 LTC2851IMS8#PBF
 MAX4571CEI+T	 MAX691ACWE+T	 MAX809TEUR+T	 MP1482SDS-LF-Z	 RCLAMP0582BQTCT
 RLZC9400	 S-24CS08AFJ-TB-1GE	 TLE8261E	 TR/3216FF1-R	 TT60F11KEM
 UBA2013T/N3	 UC382TDTR-3	 V300C28C150BN2	 W25Q80DVSSIG	 YST35-21P42G

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited