
 <p>A Renesas Company</p>	<p>X5001PI-2.7A</p>
	<p>Manufacturer Part Number: X5001PI-2.7A</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC SUPERVISOR CPU 8-DIP</p> <p>Datasheets:  X5001PI-2.7A.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X5001PI-2.7A
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 8-DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.92V
Packaging	Tube

X5001PI-2.7A is New Original in Stock, Search X5001PI-2.7A Datasheets, PDF, Inventory at Y-IC.com Online, Order X5001PI-2.7A Intersil with warrantied and confidence. RFQ X5001PI-2.7A : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5001PI-2.7 Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PI Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PIZ-2.7A Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PIZ Intersil IC SUPERVISOR CPU 8-DIP</p>
 <p>X5001PIZ-4.5A Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PIZ-2.7 Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PI-4.5A Intersil IC SUPERVISOR CPU 8-DIP</p>	 <p>X5001PZ-2.7 Intersil IC SUPERVISOR CPU 8-DIP</p>

Hot Parts

[More](#)

- | | | | | |
|--|--|--|---|--|
|  06035A181JA2A |  08051A910JAT2A |  08053C103KAJ2A |  0805ZC471MAT2A |  A50L-0001-0337 |
|  ADG406BPZ |  APIODCA1-003 |  BCM56504B2KEBG |  BO48F160M24 |  BSTR60133L |
|  C0603C0G1E620G |  CP0603A1800LNTR |  DS26LV32ATM |  DT400N04KOF |  DTA144ESTP |
|  EP5358HUI |  FAN4274IMU8X |  GRM1555C1H430GZ01D |  GRM2165C1H201JA01D |  HA12229F |
|  IRG7IA13UPBF |  ISL6412IRZ-TK |  LM20134MHX |  LT1614CS8 |  MAX14688EWC+T |
|  MAX4211AEUE+ |  MAX490ESA |  MAX6328UR31-T |  MG400Q1US11SMZC77 |  MIG100Q6CMB1X |
|  MMBZ5244B |  N310CH20 |  NDC7002N |  P28F010-120 |  PC3SD12NXZA |
|  PCF5079HK/C/1 |  PCM1807PW |  RQJ0306FQDQS |  SAYEV836MA0F00R12 |  SI8802DB-T2-E1 |
|  SN74AHC2G14HDCTR |  SP810EK-L-4-4/TR |  SS5P4-M3/86A |  SUM55N03-16P-E3 |  T2401N52TOH |
|  T520S1100T |  TPS5510DR |  TSH22IDT |  UM100CDY-9 |  VI-J6D-IW |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited