

	<h2 style="color: red;">X1286V14IT1</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">X1286V14IT1</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Intersil</a>
	<b>Part of Description:</b>	IC RTC CLK/CALENDAR I2C 14-TSSOP
<b>Datasheets:</b>	 <a href="#">X1286V14IT1.pdf</a>	
<b>RoHs Status:</b>	Contains lead / RoHS non-compliant	
<b>Stock Condition:</b>	New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	X1286V14IT1
Manufacturer	Intersil
Description	IC RTC CLK/CALENDAR I2C 14-TSSOP
Category	Integrated Circuits (ICs) > Clock/Timing - Real Time
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Clock/Calendar
Features	Alarm, Leap Year, Supervisor, Watchdog Timer
Interface	I <sup>2</sup> C, 2-Wire Serial
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Voltage - Supply	2.7 V ~ 5.5 V
Memory Size	-
Time Format	HH:MM:SS:hh (12/24 hr)
Date Format	YY-MM-DD-dd
Voltage - Supply, Battery	1.8 V ~ 5.5 V
Current - Timekeeping (Max)	10µA ~ 20µA @ 2.7V ~ 5V
Packaging	Tape & Reel (TR)

X1286V14IT1 is New Original in Stock, Search X1286V14IT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X1286V14IT1 Intersil with warrantied and confidence. RFQ X1286V14IT1 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>X1286V</b> XICOR X1286V XICOR</p>	 <p><b>X1288S16-2.7A</b> Intersil IC RTC CLK/CALENDAR I2C 16-SOIC</p>	 <p><b>X1286A8T1</b> Intersil IC RTC CLK/CALENDAR I2C 8-SOIC</p>	 <p><b>X1288S16-2.7</b> Intersil IC RTC CLK/CALENDAR I2C 16-SOIC</p>
 <p><b>X1286V14I</b> Intersil IC RTC CLK/CALENDAR I2C 14-TSSOP</p>	 <p><b>X1286V14T1</b> Intersil IC RTC CLK/CALENDAR I2C 14-TSSOP</p>	 <p><b>X1288S</b> XICOR X1288S XICOR</p>	 <p><b>X1286A8Z</b> XICOR X1286A8Z XICOR</p>

### Hot Parts

More

- |                     |                     |                       |                    |                      |
|---------------------|---------------------|-----------------------|--------------------|----------------------|
| ⊕ 08053A151FAT2A    | ↔ 0805VA180KAT2A    | ⇒ 12065C242KAT2A      | D AD708BRZ-REEL    | ↗ AP7311-20WG-7      |
| ⊖ BU4011BF-E2       | ⊕ BZT52C2V4-13-F    | D BZX84C10-7-F        | ⇒ CAT93C56SIT-FB   | ↗ CC0603JRNPO9BN180  |
| ⊕ CC0805JRNPO9BN102 | ⊖ CC0805KKX5R7BB475 | ⊕ CD216A-B120L        | ↔ CD74HCT08M96     | ↗ CRA12E0803-47R     |
| D GMJ316BB7474KLHT  | ⊕ GP1FAV31TK0F      | ⊖ GRJ31MR72A224KE01L  | ⊕ HI100522NJT      | ↗ HN-20CAW           |
| ⇒ HT-120DS          | ↔ HT-155HQ/GQ       | ⊕ ICE3A5565P          | ⊖ IP-233-CY        | ↗ IR21368J           |
| ↔ LM3674MF-1.2/NOPB | ⇒ LMV711IDCKRG4     | D LT3684EDD#TRPBF     | ⊕ LTC3456EUF#TRPBF | ⊖ MB81C4256A-60P     |
| ⊕ MMSZ5234BF        | D MX29LV640MBTC-90  | ⇒ NTTFS4941N          | ↔ SAA7391HL        | ↗ SC5073A1S-G        |
| ⊖ SE4120L-R         | ⊕ SI2366DS-T1-GE3   | ↔ SLF7045T-6R8M1R7-PF | ⇒ SMBT1296LT3G     | ↗ SMCJ30A-7010E3/9AT |
| ⊕ SPD26N06S2L-35    | ⊖ SPH3015H6R8MT     | ⊕ STD40NF10           | D STPS3045CR       | ↗ TB1203AP           |
| ↔ TK11236AM         | ⊕ USB0412-LF-T7     | ⊖ V24A48C400B3        | ⊕ VI-211-CU        | ↗ VS-12CWQ04FNTRR-M3 |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited