








|   |   |
|---|---|
|  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> | <h2 style="color: red;">HN58V66AFP-10</h2>  |
|   | <p><b>Manufacturer Part Number:</b> <a href="#">HN58V66AFP-10</a></p> <p><b>Manufacturer/Brand:</b> HITACHI</p> <p><b>Part of Description:</b> HITACHI SOP28</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 1100 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation.<br/>See specs for product details.</p>  |   |

### Specifications

|              |  |
|--------------|--|
| Part Number  | <a href="#">HN58V66AFP-10</a>                                      |
| Manufacturer | HITACHI  |
| Description  | HITACHI SOP28  |
| Category     | <a href="#">Integrated Circuits (ICs) &gt; Specialized Hot ICs</a> |
| Part Status  | 1100 pcs Stock   |
| Series       | -  |
| RoHs Status  | Lead free / RoHS Compliant   |
| Condition    | New Original Stock   |
| Warranty     | 100% Perfect Functions   |
| Lead Time    | 2-3days after payment.   |
| Payment      | PayPal / Telegraphic Transfer / Western Union                      |
| Shipping by  | DHL / Fedex / UPS  |
| Port         | HongKong   |
| RFQ Email    | <a href="mailto:Info@Y-IC.com">Info@Y-IC.com</a>                   |

HN58V66AFP-10 is New Original in Stock, Search HN58V66AFP-10 Datasheets, PDF, Inventory at Y-IC.com Online, Order HN58V66AFP-10 with warrantied and confidence. RFQ  
HN58V66AFP-10 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

|   |   |   |   |
|---|---|---|---|
| <p>In:</p>  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V65AFP-10</b><br/>RENESAS<br/>RENESAS SOP-28</p> |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58W241000FPI#S0</b><br/>RENESAS<br/>RENESAS SOP-8</p> |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V66AFP-10Z</b><br/>HITACH<br/>HITACH SOP</p> |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V66AP-10</b><br/>HITACHI<br/>HITACHI DIP</p>    |
|  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V65AP-10</b><br/>HITACHI<br/>HITACHI DIP28</p>              |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V65AT-10SR</b><br/>HITACHI<br/>HITACHI TSOP</p>     |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V65AFPI-10</b><br/>HIT<br/>HIT SOP28</p>     |  <p>Not Actual Photo<br/>YIC International Co., Limited.</p> <p><b>HN58V66AT-10</b><br/>RENESAS<br/>RENESAS TSOP28</p> |

### Hot Parts

[More](#)

|                      |                    |                     |                      |                 |
|----------------------|--------------------|---------------------|----------------------|-----------------|
| 1812WC222JAT1A       | AA4006GTR-E1       | AP4034AGM-HF        | APL5301-33DC-TRL     | AUIRF2804LRL306 |
| B78108S1154J         | BD3180FV           | C3216C0G2J222J115AA | CGA4J3X5R1C335K125AB | CL21X106KQQNNG  |
| CM502-RI02           | DTA014TEB          | EMIF10-LCD01F2AU    | FCPF9N60NT           | FDN5632N-F085   |
| FS200R06KL4          | GRM0335C1H160JA01D | GRM3166S1H271JZ01D  | HFA16TA60CSTRR       | KTY82/110       |
| LDA212G4410K-283     | LM4917MTX/NOPB     | LP324MX/NOPB        | LQW18AN3N6D00D       | LT3465AES6      |
| MB88146APFV-G-BND-ER | MC10H352FNR2       | MCD255-16IO1B       | MIG20J805H190        | MMBZ5V6B        |
| MMZ1005F121ET00      | P2703ACL           | PCA9504ADGG         | PI6C4911505LIEX      | R355CH08        |
| R4111040             | RT9193-15PB        | SF24D12-10W(B)      | T198N600TOC          | T835-600B-TR    |
| TC7SET126F           | TE28F800B3TA110    | TPS5633PWPR         | TT104N14KOF-K        | UMK105BJ222MV-F |
| UMK105CG560KV-F      | US1J-E3/61T        | X9317ZS8Z-2.7       | XC6118C29CGR-G       | XRT5997IVTR-F   |

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited