
 <p>A Renesas Company</p>	<p>HI1-0548-2</p>
	<p>Manufacturer Part Number: HI1-0548-2</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC MULTIPLEXER 8X1 16CDIP</p> <p>Datasheets: HI1-0548-2.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	








Specifications

Part Number	HI1-0548-2
Manufacturer	Intersil
Description	IC MULTIPLEXER 8X1 16CDIP
Category	Integrated Circuits (ICs) > Interface - Analog Switches,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-55°C ~ 125°C (TA)
Package / Case	16-CDIP (0.300", 7.62mm)
Supplier Device Package	16-CDIP
Number of Circuits	1
-3db Bandwidth	-
Multiplexer/Demultiplexer Circuit	8:1
Switch Circuit	-
On-State Resistance (Max)	1.5 kOhm
Voltage - Supply, Single (V+)	-
Voltage - Supply, Dual (V±)	±15V
Channel-to-Channel Matching (ΔRon)	105 Ohm
Switch Time (Ton, Toff) (Max)	500ns, 500ns
Charge Injection	-
Channel Capacitance (CS(off), CD(off))	10pF, 25pF
Current - Leakage (IS(off)) (Max)	30pA (Typ)
Crosstalk	-
Packaging	Tube

HI1-0548-2 is New Original in Stock, Search HI1-0548-2 Datasheets, PDF, Inventory at Y-IC.com Online, Order HI1-0548-2 Intersil with warrantied and confidence. RFQ HI1-0548-2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>HI1-0539-5 Intersil IC MULTIPLEXER 4X1 16CDIP</p>	 <p>HI1-1818A-2 Intersil IC MULTIPLEXER 8X1 16CDIP</p>	 <p>HI1-0547-5 Intersil IC MULTIPLEXER DUAL 8X1 28CDIP</p>	 <p>HI1-200-5 HARRIS HARRIS CDIP14</p>
 <p>HI1-1818A-5 H HI1-1818A-5 H</p>	 <p>HI1-0546-5 Intersil IC MULTIPLEXER 16X1 28CDIP</p>	 <p>HI1-0548-4 INTERSIL HI1-0548-4 INTERSIL</p>	 <p>HI1-0548-5 Intersil IC MULTIPLEXER 8X1 16CDIP</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|----------------------|----------------------|----------------------|--------------------|
| ⊛ 02013A4R5CAT2A | ↔ 02016G153ZAT2A | ⇒ 06031C222J4T2A | D 08051A391JAT2A | ⇒ 1206GC331KAT1AJ |
| ⊣ 293D225X9035C2TE3 | ⊛ A3972SBT | D AD8617ARMZ-REEL | ⇒ AMK316BJ107ML-T | ⇒ AP130-28WL-7 |
| ⊛ AP1521WG-7 | ⊣ APTM50AM17F | ⊛ AR904P10 | ↔ AT49BV162A-70TI | ⇒ BAT43XV2 |
| D BCM5754KFBG | ⊛ BCR08AS12AUL | ⊣ BD8629FS-E2 | ⊛ BR24CO1AFV-WE2 | ⇒ BTA06-600CRG |
| ⇒ C0603C0G1E270K030BA | ↔ C1608CH1H331J080AA | ⊛ CA1a-DC12V-B | ⊣ CC1206JKNPOCBN180 | ⇒ CL31C391JBCNNNC |
| ↔ GJM1555C1H3R4CB01D | ⇒ GMK107BJ105MAHT | D GRM0336S1E7R0DD01D | ⊛ GRM1556R1H2R2CZ01D | ⊣ IPB14N03LAG |
| ⊛ IRFP150M | D IXFH40N30Q | ⇒ LP2985IM5-3.3/NOPB | ↔ MABACT0017 | ⇒ MBR30040 |
| ⊣ MC74VHC1G02DFT2G | ⊛ ME8107-G | ↔ MMBZ5247BLT1G | ⇒ P1101SA-L | ⇒ PL611-30-L44SC-R |
| ⊛ RQA130N03FD5TB | ⊣ RS-03K334FT | ⊛ SF14-1575F5UU07 | D SSM3J15F | ⇒ TMK063CH050DP-F |
| ↔ TMP303ADRLRG4 | ⊛ TOP271VG | ⊣ VI-27Z-CW | ⊛ VI-J0L-IY | ⇒ VI-J50-CX-01 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited