

 A Renesas Company	X40431V14I-AT1
	Manufacturer Part Number: X40431V14I-AT1
	Manufacturer/Brand: Intersil
	Part of Description: IC VOLT MON TRPL EEPROM 14-TSSOP
Datasheets:	 X40431V14I-AT1.pdf
RoHs Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	X40431V14I-AT1
Manufacturer	Intersil
Description	IC VOLT MON TRPL EEPROM 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	3
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.7V, 2.9V, 4.6V
Packaging	Tape & Reel (TR)

X40431V14I-AT1 is New Original in Stock, Search X40431V14I-AT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40431V14I-AT1 Intersil with warrantied and confidence. RFQ X40431V14I-AT1 : Info@Y-IC.com

You May Be Also Be interested

In:

 X40431V14I-C Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40431V14I-A Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40431V14-B Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40434S14-A Intersil IC VOLT MON TRPL EEPROM 14-SOIC
 X40431V14-CT1 Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40431V14-C Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40431V14I-B Intersil IC VOLT MON TRPL EEPROM 14-TSSOP	 X40431V14I-CT1 Intersil IC VOLT MON TRPL EEPROM 14-TSSOP

Hot Parts

More

- | | | | | |
|-------------------|----------------------|--------------------|--------------------|--------------------|
| 0805YA821JAT2A | 12065A181FAT2A | 12103E474ZAT2A | D 1812CC222KAZ1A | 6MBP35XSD060-5 |
| AD9833WBRMZ-REEL7 | AK8130-E2 | AK93C45AV-L | AM29F040-120EC | AN2512S-E2 |
| AP4310AMTR-E1 | AR8035-2 | BR93LC46-W | C0603JB1A474M030BC | CBS3502412 |
| D CDBA140LL-G | CGA4J3X8R1H224M125AD | CPT50125 | CQ0805JRNPOYBN220 | FDB4030L |
| FDMS8020 | FGB3040CS_F085 | FP0100N8-G | GRM1885C2A181GA01D | IB0505LS-1W |
| LM2842XMKX-ADJL | LT1117IST-5#TRPBF | D LTC2052CGN#TRPBF | M24C16-WMN6/KKS | MAAM-009116-TR3000 |
| ME501C1P | MIC2551BMLTR | MMSZ5244B | NDT451AN | NESG240033-TB |
| PSKT72/08IO8 | RF3374TR7 | RL3720T-R022-F | S-29U131ADFE-TB | SI4944DY-T1-E3 |
| SKMD105F12 | SKY85712-21 | SM5S13AHE3/2D | D SMAJ160CA-E3/61 | SN74F04DBR |
| SSCD104TS | TPS51727RHAT | UPD780102HMC | V300B5C200BG3 | WP-90138L2 |