


| | |
|---|---|
|  <p>Not Actual Photo YIC International Co., Limited.</p> | <p>BAT754C</p> |
| | <p>Manufacturer Part Number: BAT754C</p> <p>Manufacturer/Brand: NXP</p> <p>Part of Description: BAT754C NXP</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 412343 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation. See specs for product details.</p> | |

Specifications

| | |
|--------------|---|
| Part Number | BAT754C |
| Manufacturer | NXP |
| Description | BAT754C NXP |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 412343 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

BAT754C is New Original in Stock, Search BAT754C Datasheets, PDF, Inventory at Y-IC.com Online, Order BAT754C with warrantied and confidence. RFQ BAT754C : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|---|--|--|--|
|  <p>BAT754C,215 Nexperia DIODE ARRAY SCHOTTKY 30V SOT23</p> |  <p>BAT754(2KW) PHILIPS PHILIPS SOT23</p> |  <p>BAT754L+115 NXP NXP SOT23-6</p> |  <p>BAT754 NXP BAT754 NXP</p> |
|  <p>BAT754A,215 Nexperia DIODE ARRAY SCHOTTKY 30V SOT23</p> |  <p>BAT754,215 Nexperia DIODE SCHOTTKY 30V 200MA SOT23</p> |  <p>BAT754C,215 Nichicon DIODE ARRAY SCHOTTKY 30V SOT23</p> |  <p>BAT754L,115 Nexperia DIODE ARRAY SCHOTTKY 30V 6TSSOP</p> |

Hot Parts

More

- | | | | | |
|----------------------|---------------------|---------------------|-------------------|----------------------|
| ⊕ 06031A100F4T2A | ↔ 06032C102KAT2A | ⇒ ACPM-7500-SG1 | D AD8519ARTZ-RL7 | ⇒ AT30TSE754A-SS8M-T |
| ⊖ BZT52C7V5T-7 | ⊕ BZX84C16CT1G | D CC0201BRNPO9BN1R2 | ⇒ CDCE906R004PWR | ⇒ CL10B272KB8SFNC |
| ⊕ CMUDM8004 | ⊖ D188S1200T | ⊕ EMIF03-SIM01 | ↔ FAN2558S10X | ⇒ GRM31CR61A106KA01L |
| D IRKL26/12 | ⊕ IRKV105/04S90 | ⊖ IRU1205-30CLTR | ⊕ ISL8325IBZ | ⇒ LM4041CQDBZR |
| ⇒ LMP2232BMM/NOPB | ↔ LQH32CN2R2M11L | ⊕ LT1091ACN8 | ⊖ LT3090EMSE#PBF | ⇒ LT3591EDDB#TRMPBF |
| ↔ LT3970EDDB#TRPBF | ⇒ LTC1197LIS8#TRPBF | D LTC4211CMS8#TR | ⊕ NCP1282BDR2G | ⊖ OPA637BP |
| ⊕ PMB5725FV1.5010ICP | D PQ1L333M2SPQ | ⇒ R920222000 | ↔ RM30TC-24 | ⇒ SBR2A40P1 |
| ⊖ SDIN4C1-8G | ⊕ SKKT210/14E | ↔ SM14PHN170 | ⇒ SMCJ16CA | ⇒ TA75324F |
| ⊕ TB62727FNG | ⊖ TMS320F28335PGFA | ⊕ TPA6017A2PWP | D UMK063CG1R8CT-F | ⇒ VI-210-01/F1 |
| ↔ VLS4012T-470MR39 | ⊕ VRF0505S-2W | ⊖ VS-16CTQ100PBF | ⊕ XP151A13A0MR | ⇒ Z8S18033VSC |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited