

 <p>A Renesas Company</p>	<p>ISL88001IE16Z-T7A</p>
	<p>Manufacturer Part Number: ISL88001IE16Z-T7A</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC VOLT SUPERVISOR 1.58V SC70-3</p> <p>Datasheets: ISL88001IE16Z-T7A.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	ISL88001IE16Z-T7A
Manufacturer	Intersil
Description	IC VOLT SUPERVISOR 1.58V SC70-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-70, SOT-323
Supplier Device Package	SC-70-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	1.58V
Packaging	Original-Reel®

ISL88001IE16Z-T7A is New Original in Stock, Search ISL88001IE16Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88001IE16Z-T7A Intersil with warrantied and confidence.
RFQ ISL88001IE16Z-T7A : Info@Y-IC.com



















































You May Be Also Be interested

In:

 <p>ISL88001IE16Z-T Intersil IC VOLT SUPERVISOR 1.58V SC-70</p>	 <p>ISL8724IRZ Intersil IC POWER SUPPLY SEQUENCER 24QFN</p>	 <p>ISL88001/2/3EVAL1Z Intersil EVAL BOARD 1 FOR ISL88001/2/3</p>	 <p>ISL88001IE16Z-TK Intersil IC VOLT SUPERVISOR 1.58V SC-70</p>
 <p>ISL88001IE18Z INTERSI ISL88001IE18Z INTERSI</p>	 <p>ISL8723IRZ-T Intersil IC POWER SUPPLY SEQUENCER 24QFN</p>	 <p>ISL8724IRZ-T Intersil IC POWER SUPPLY SEQUENCER 24QFN</p>	 <p>ISL88001IE17Z-T7A Intersil IC VOLT SUPERVISOR 1.67V SC70-3</p>

Hot Parts

[More](#)

- | | | | | |
|---|--|---|--|--|
|  20369-001 |  7443330100 |  APU1117K-25-HF-3TR |  B511SE-2T |  BA5912AFP-YE2 |
|  BAT64-05WE6327 |  BSZ035N03MSG |  C1005X8R1E153M050BB |  C1608X5R0J155M080AB |  CC1206GRNP09BN100 |
|  D668N2000T |  EWIXP425ABDT |  FP15R12W1T4-B11 |  FSA1257L8X |  GRM2165C1H122FA01D |
|  D HD64F2138AFA20V |  ICS9UMS9610CKLFT |  IPB025N08N3G |  IRF2807ZLPBF |  IRF9321TRPBF |
|  IRFR6215TRL |  ISL6426CV |  IXTQ150N06P |  KP1010/KPC817C |  LB2518T102M |
|  LM5109BMAX/NOPB |  LMS1585ACS-3.3 |  LT1181CS |  LT6703IDC-2#TRPBF |  LTC4261CGN#PBF |
|  LTM8008-ETV#PBF |  M0736LC450 |  M29W160EB90N1 |  MAX6383LT43D3+ |  MMBZ5258BLT1 |
|  N510SH20 |  NCP500SN25T1G |  PI74FCT162244CTVX |  PSMN09-25YLC |  PVG612ASPBF |
|  Q476-A-3 |  SI4892DY-T1-E3. |  SMAJ85CA-13-F |  SS10PH10-M3/86A |  TC7SZ125FU |
|  TLC272ACP |  TPS2053BDR |  UPC3219GV |  VS-30WQ04FNTR-M3 |  X0202MN-5B4A |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited