









 A Renesas Company	ISL88001IH31Z-T7A
	Manufacturer Part Number: ISL88001IH31Z-T7A
	Manufacturer/Brand: Intersil
	Part of Description: IC VOLT SUPERVISOR 3.09V SOT23-3
	Datasheets:  ISL88001IH31Z-T7A.pdf
	RoHS Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	ISL88001IH31Z-T7A
Manufacturer	Intersil
Description	IC VOLT SUPERVISOR 3.09V SOT23-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	TO-236-3, SC-59, SOT-23-3
Supplier Device Package	SOT-23-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	3.075V
Packaging	Original-Reel®



















































ISL88001IH31Z-T7A is New Original in Stock, Search ISL88001IH31Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88001IH31Z-T7A Intersil with warrantied and confidence. RFQ ISL88001IH31Z-T7A : Info@Y-IC.com

You May Be Also Be interested

In:  ISL88001IH29Z-T Intersil IC VOLT SUPERVISOR 2.92V SOT23-3	 ISL88001IH44Z-T Intersil IC VOLT SUPERVISOR 4.38V SOT23-3	 ISL88001IH44Z-TK Intersil IC VOLT SUPERVISOR 4.38V SOT23-3	 ISL88001IH44Z-T7A Intersil IC VOLT SUPERVISOR 4.38V SOT23-3
 ISL88001IH29Z-T7A Intersil IC VOLT SUPERVISOR 2.92V SOT23-3	 ISL88001IH31Z-T Intersil IC VOLT SUPERVISOR 3.09V SOT23-3	 ISL88001IH31Z-TK Intersil IC VOLT SUPERVISOR 3.09V SOT23-3	 ISL88001IH46Z-T Intersil IC VOLT SUPERVISOR 4.64V SOT23-3

Hot Parts

[More](#)

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited