




	<b>X5323S8Z</b>
	<b>Manufacturer Part Number:</b> <a href="#">X5323S8Z</a>
	<b>Manufacturer/Brand:</b> <a href="#">Intersil</a>
	<b>Part of Description:</b> IC CPU SUPERV 32K EE 8-SOIC
<b>Datasheets:</b>  <a href="#">X5323S8Z.pdf</a>	<b>RoHS Status:</b>  Lead free / RoHS
<b>Stock Condition:</b> Compliant New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	<a href="#">X5323S8Z</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC CPU SUPERV 32K EE 8-SOIC
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tube

X5323S8Z is New Original in Stock, Search X5323S8Z Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323S8Z Intersil with warrantied and confidence. RFQ X5323S8Z : [Info@Y-IC.com](mailto:Info@Y-IC.com)








































### You May Be Also Be interested

In:

 <p><b>X5323S8IZ-4.5AT1</b> Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p><b>X5323S8Z-4.5</b> XICOR X5323S8Z-4.5 XICOR</p>	 <p><b>X5323S8Z-2.7AT1</b> Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p><b>X5323S8Z-2.7T1</b> Intersil IC CPU SUPERV 32K EE 8-SOIC</p>
 <p><b>X5323S8IZ-4.5A</b> Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p><b>X5323S8IZT1</b> Intersil IC CPU SUPERVISOR 32K EE 8-SOIC</p>	 <p><b>X5323S8Z-2.7</b> Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p><b>X5323S8T1</b> Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>

### Hot Parts

[More](#)

- |  |  |  |  |  |
|--|--|--|--|--|
|  1206CC102KAJ1A     |  1808AC102MATME     |  6DI150M-120        |  6DI15MS-050         |  ADD5207ACPZ-RL       |
|  APTGT75X120E3G     |  ASMT-QTB0-0AA02    |  AT25040B-SSH-L-T   |  C1005C0G1H101K050BA |  CGA4J2X5R1H224M125AA |
|  CPDV3-5V0U         |  ELM89181BB-S       |  ER3J-T/R           |  FAN6602RM6X         |  FI-WE31P-HFE-E1500   |
|  GCM1885C1H5R7DA16D |  GJM1555C1H1R2CB01D |  HCPL2630           |  IMP1812R-15/T       |  IR3596MTRPBF.        |
|  IRFD9210PBF        |  IRKT71/10AS90      |  LTC3406BES5-1.2    |  LTC4065EDC#TRMPBF   |  M62006FP             |
|  MAZS0330LL         |  MEM2012W211RT001   |  MSM56V16160F-10TSK |  NP36P04SDG-E1-AY    |  NPR1TTE150RJ         |
|  P2803BCG           |  P290B1101          |  PMEG4005AEV        |  R1448NS14L          |  RM20TNA-2H           |
|  RP1203-18PVL       |  SIP21101DR-33-E3   |  SIRA18DP-T1-GE3    |  SMCJ70A-E3/57       |  SPB02N60S5           |
|  ST25C01FM1         |  T3801N18TOF        |  TL16C554A          |  TL317CDR            |  TN25F110-5           |
|  V300B12H250AL      |  V375A3V3C264BG3    |  VND5E050MK         |  XC61CN2502MRN       |  Z322402              |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited