








 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">X40411V8-CT1</h2>
	<p>Manufacturer Part Number: X40411V8-CT1</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC VOLTAGE MON DUAL W/SUP 8TSSOP</p> <hr/> <p>Datasheets:  X40411V8-CT1.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	X40411V8-CT1
Manufacturer	Intersil
Description	IC VOLTAGE MON DUAL W/SUP 8TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	8-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	8-TSSOP
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	2
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.7V, 2.9V
Packaging	Tape & Reel (TR)









































X40411V8-CT1 is New Original in Stock, Search X40411V8-CT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40411V8-CT1 Intersil with warrantied and confidence. RFQ X40411V8-CT1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>X40411V8I-AT1 Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8I-A Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8-BT1 Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8-AT1 Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>
 <p>X40411V8I-B Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8-B Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8I-C Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>	 <p>X40411V8-C Intersil IC VOLTAGE MON DUAL W/SUP 8TSSOP</p>

Hot Parts

[More](#)

 08053C183JAT2A	 100B1R5CT500XT	 156120GS75300	 18085A272JAT2A	 2225CC823MAT1A
 6DI75MB-060	 AMS2907L-1.8	 BCR183SE6327	 CLC1005ISO8MTR	 CM150RX-24S1
 D255N200B	 DF100AA140	 DS90LV017ATM	 EMC2113-1-AP-TR	 FDP060N08AO
 D FDFPF190N15A	 FS150R12KS4	 GR731AW0BB153KW01D	 GRM1555C1H9R2WZ01D	 GRM1885C2A4R5CA01D
 IRG4IBC10UD	 LBMF1608T220K	 LTC2050HS6#TRMPBF	 MAX6008AESA+T	 MAX815LCSA
 MBRF2045CT	 MIC2211-OOBML	 MSD7818-L2	 N0180SH140	 N1467NS160
 N600CH15LOO	 NJM2870F45-TE1	 NRF24AP20	 PCF2119RU/F2	 PCF8523T/1
 PD25F-160	 PD413PI2GEF5	 QSW025A0B61-14PHZ	 RT9261-30CB.	 RX-8564LC
 SN74CBTD3861DWR	 SPMWHT541MLSXAUKS6	 ST303C10CFJ1	 TEP5LA1A336B8R	 TLE8110EE
 TOP209GN	 TSB43AB23PDTG4	 V300C12C150A3	 VI-B31-CU-02	 VVO60-16I07

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited