 <p>Not Actual Photo YIC International Co., Limited.</p>	<p>BC856LT1 3B</p>
	<p>Manufacturer Part Number: BC856LT1 3B</p> <p>Manufacturer/Brand: CJ</p> <p>Part of Description: BC856LT1 3B CJ</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 6000 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	BC856LT1 3B
Manufacturer	CJ
Description	BC856LT1 3B CJ
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	6000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

BC856LT1 3B is New Original in Stock, Search BC856LT1 3B Datasheets, PDF, Inventory at Y-IC.com Online, Order BC856LT1 3B with warrantied and confidence. RFQ BC856LT1 3B : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>BC856S,115 Nexperia TRANS 2PNP 65V 0.1A 6TSSOP</p>	 <p>BC856G-B Original BC856G-B Original</p>	 <p>BC856LT1G ROHM BC856LT1G ROHM</p>	 <p>BC856CW-G Comchip Technology TRANS PNP 65V 100A SOT323</p>
 <p>BC856L SOT23 SOT23 UTC</p>	 <p>BC856E ST ST SOT-523</p>	 <p>BC856S E6327 SOT363 SOT363 INFINEO</p>	 <p>BC856S NXP BC856S NXP</p>

Hot Parts More

- | | | | | |
|---------------------|-----------------------|-----------------------|----------------------|------------------------|
| ⚙️ 0603YC102J4Z2A | ➡️ 08055A221FA12A | ➡️ 1808AC103MATBE | D 1812AA222JAT1AJ | ➡️ AAT1164C-Q5-T |
| ⚡️ ADP3339AKC-5-RL7 | ⚙️ APT17ZTR-G1 | D AV25-48S03 | ➡️ BSP296NH6327 | ➡️ BZG05C3V9TR3 |
| ⚙️ BZX384C13-E3-08 | ⚡️ C420C222J1G5TA7200 | ⚙️ CC0603CRNPO9BN2R7 | ➡️ CY2308SXC-2 | ➡️ DF10S-E3/77 |
| D FA-100PY | ⚙️ FF150R10K | ⚡️ GRM1555C1H241GA01D | ⚙️ HMS91C7316 | ➡️ HYB18T1G800BF-3.7 |
| ➡️ IPB80N06S2L-07 | ➡️ IRKD166/14 | ⚙️ IRLZ24S/NS | ⚡️ IXGH12N120A3 | ➡️ J0026D01ENL |
| ➡️ L6384ED013TR | ➡️ LL1608-F4N7S | D LT1134AISW | ⚙️ LTC3824IMSE#TRPBF | ⚡️ LTC4210-1IS6#TRPBF |
| ⚙️ MAX4462TETT+T | D MC14069UBD | ➡️ MCR01MRTJ202 | ➡️ MDF5N50BTH | ➡️ MM3122FPRE |
| ⚡️ MT6612N/A | ⚙️ NSBC115EDXV6T1 | ➡️ OPA691IDBVR | ➡️ P027QH10 | ➡️ PVG3A104C01R00 |
| ⚙️ S553-3873-32 | ⚡️ SMC3K30CA | ⚙️ SML4730/2P | D STPS30175CW | ➡️ TC7SH08FUTE85L |
| ➡️ TEPSLC1A157M12R | ⚙️ TL431BIDR | ⚡️ TLA-6T103-T | ⚙️ TS39152CM5 | ➡️ UPD78F0078YGC-8BS-A |