









	<p>HIP6301VCBZ-T</p>
	<p>Manufacturer Part Number: HIP6301VCBZ-T</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC REG CTRLR BUCK 20SOIC</p> <p>Datasheets: PDF HIP6301VCBZ-T.pdf</p> <p>RoHS Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	HIP6301VCBZ-T
Manufacturer	Intersil
Description	IC REG CTRLR BUCK 20SOIC
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Output Type	PWM Signal
Package / Case	20-SOIC (0.295", 7.50mm Width)
Supplier Device Package	20-SOIC
Function	Step-Down
Frequency - Switching	280kHz
Number of Outputs	4
Output Configuration	Positive
Voltage - Supply (Vcc/Vdd)	4.75 V ~ 5.25 V
Topology	Buck
Control Features	Enable, Frequency Control, Power Good
Output Phases	4
Duty Cycle (Max)	-
Synchronous Rectifier	-
Clock Sync	No
Serial Interfaces	-
Packaging	Tape & Reel (TR)

HIP6301VCBZ-T is New Original in Stock, Search HIP6301VCBZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order HIP6301VCBZ-T Intersil with warrantied and confidence. RFQ
HIP6301VCBZ-T : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>HIP6302CB-1T HARR1S HIP6302CB-1T HARR1S</p>	 <p>HIP6301VCBZ Intersil IC REG CTRLR BUCK 20SOIC</p>	 <p>HIP6302B INTERSI INTERSI SOP-16</p>	 <p>HIP6302CB-TS2495 INTERSI INTERSI SOP16</p>
 <p>HIP6301CBZ-T Intersil IC REG CTRLR BUCK 20SOIC</p>	 <p>HIP6301EVAL2 Intersil EVALUATION BOARD HIP6301</p>	 <p>HIP6302CB Intersil IC REG CTRLR BUCK 16SOIC</p>	 <p>HIP6302CB-T Intersil IC REG CTRLR BUCK 16SOIC</p>

Hot Parts

More

- | | | | | |
|---------------------|-----------------------|--------------------|-----------------------|----------------------|
| ⊛ 12067A2R2CAT2A | ↔ 1210CC473KAT1A | ⇒ 750510061 | D AP2625GY | ⇒ ATF747X25D |
| ⊣ B39192-B5104-U410 | ⊛ BQ24060DRC | D BUK75150-55A | ⇒ C1608X5R0J335K080AB | ⇒ CC1206JKNPODBN101 |
| ⊛ CY7C185-15VI | ⊣ FI-RE51S-HF-J-R1500 | ⊛ FZ400R17KE3-S4 | ↔ GJM1555C1H8R8DB01D | ⇒ GQM1555C2D4R0WB01D |
| D HA1-2541-2 | ⊛ HS16A3F06 | ⊣ ICE40LP1K-CM36TR | ⊛ INA271AQDRQ1 | ⇒ IRU1150IS |
| ⇒ LQW18CNR39J00D | ↔ LT1168IS8#TRPBF | ⊛ LTA1004MYB | ⊣ LTC1504ACS8#TRPBF | ⇒ LTC3374IUHF#PBF |
| ↔ M3062LFGPPF#U5C | ⇒ MAX15013AASA+T | D MDU5693VRH | ⊛ MIC39500-2.5BU | ⊣ MM3123APRE |
| ⊛ N87C257-150V10 | D PS48M3V3CP4 | ⇒ PYT230PIV1400 | ↔ QMK212B7332KD-T | ⇒ R2619ZD21L |
| ⊣ RJK0304DPB | ⊛ RKZ6.2B2KJR1Q | ↔ RT9050-33GB | ⇒ SAB8031A-P | ⇒ SN74HC32ANSR |
| ⊛ SY88289ALMG | ⊣ T380N16TOF | ⊛ TD66N16KOF | D TL432WHP | ⇒ TLC7135CN |
| ↔ TOP254EG | ⊛ UPA2450BTL-E1 | ⊣ VI-223-EW/S | ⊛ WM8740SEDS/RV | ⇒ X9241AWVI |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited