









	<h2 style="color: red;">EL5001ILZ-T13</h2>	
	Manufacturer Part Number:	EL5001ILZ-T13
	Manufacturer/Brand:	Intersil
	Part of Description:	IC CLOCK DRIVER 6-CHAN 20-QFN
Datasheets:	 EL5001ILZ-T13.pdf	
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	EL5001ILZ-T13
Manufacturer	Intersil
Description	IC CLOCK DRIVER 6-CHAN 20-QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Application
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Frequency - Max	-
Package / Case	20-VFQFN Exposed Pad
Supplier Device Package	20-QFN (4x4)
Number of Circuits	1
Voltage - Supply	3.3V
Output	-
Main Purpose	LTPS LCD Clock Drivers
Input	CMOS, TTL
PLL	No
Ratio - Input:Output	6:6
Differential - Input:Output	Yes/No
Packaging	Tape & Reel (TR)

EL5001ILZ-T13 is New Original in Stock, Search EL5001ILZ-T13 Datasheets, PDF, Inventory at Y-IC.com Online, Order EL5001ILZ-T13 Intersil with warrantied and confidence. RFQ
EL5001ILZ-T13 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>EL5001IL-T13 Intersil IC CLOCK DRIVER 6-CHAN 20-QFN</p>	 <p>EL5001ILZ-T7 Intersil IC CLOCK DRIVER 6-CHAN 20-QFN</p>	 <p>EL5001IL-T7 Intersil IC CLOCK DRIVER 6-CHAN 20-QFN</p>	 <p>EL5001ILZ INTERSIL EL5001ILZ INTERSIL</p>
 <p>EL5001IRE-T13 Intersil IC CLOCK DRIVER 6-CHAN 20-HTSSOP</p>	 <p>EL5001IRE-T7 Intersil IC CLOCK DRIVER 6-CHAN 20-HTSSOP</p>	 <p>EL5001IL Intersil IC CLOCK DRIVER 6-CHAN 20-QFN</p>	 <p>EL5001IREZ Intersil IC CLOCK DRIVER 6-CHAN 20-HTSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|-------------------|------------------|-----------------------|-----------------------|----------------------|
| ⊛ 06035A391MAT2A | ↔ 12062A4R7CAT2A | ↔ 12065C472KHT1A | D 12102U391JAT2A | ↔ 1812CA471KAT9A |
| ↳ 2560TKAT-87.5M | ⊛ 3D5RN15-15 | D AMC431BDBT | ↔ AOZ8001AJI-05 | ↔ APTGT35DA120D1 |
| ⊛ B39321R981U410 | ↳ BWR-12/125-D48 | ⊛ C0603X6S0G334M030BC | ↔ C1608COG1H181K080AA | ↔ CL10C150KB8NNNC |
| D CR400EX-12 | ⊛ D5NL782M0P1JZ | ↳ EC10FW40-TE12L | ⊛ F1215S-W1 | ↔ F1856D1000 |
| ↔ FAN2108EMPX | ↔ FDMC7692 | ⊛ FZ1000R33HL3 | ↳ GRM033R71E102KA01J | ↔ GRM1556P1H7R7CZ01D |
| ↔ IRGSL15B60KD | ↔ LD06SC101KAB1A | D LM3639TMX | ⊛ LTC4066EUF#TRPBF | ↳ M93C56-WMN6T |
| ⊛ MAX774CSA | D MAX9372EUA+ | ↔ MF-NSMF020-2 | ↔ MIC9131BQS | ↔ PS20341-GP |
| ↳ RC0402JR-074M7L | ⊛ RC1117DX | ↔ SI4804CDY-T1-GE3 | ↔ SI9182DH-28-TI | ↔ SN74AUP1G97DRLR |
| ⊛ TISP4219J3BJR-S | ↳ TM25TA-H | ⊛ TMK063CG040CPGF | D TPS77633PWPR | ↔ TRF4900PW |
| ↔ ULN2803APG | ⊛ VI-2T3-MW | ↳ VI-J44-E | ⊛ Z8623012SSC00TR | ↔ ZXRE125DFTA |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited