

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">R1172S261B-E2-F</h2>
	<p><b>Manufacturer Part Number:</b> R1172S261B-E2-F</p> <p><b>Manufacturer/Brand:</b> RICOH</p> <p><b>Part of Description:</b> RICOH HSOP-6J</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 3500 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	R1172S261B-E2-F
Manufacturer	RICOH
Description	RICOH HSOP-6J
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	3500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

R1172S261B-E2-F is New Original in Stock, Search R1172S261B-E2-F Datasheets, PDF, Inventory at Y-IC.com Online, Order R1172S261B-E2-F with warranted and confidence. RFQ R1172S261B-E2-F : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>R1172S281D-E2-FE</b> RICOH RICOH SOT89</p>	 <p><b>R1173D001D</b> RICOH RICOH HSON-6</p>	 <p><b>R1172S181B-E2-F</b> RICOH RICOH HSOP6</p>	 <p><b>R1172S331D-E2-F</b> RICOH RICOH SOP</p>
 <p><b>R1172S151B-E2-F</b> RICOH RICOH SOP-6</p>	 <p><b>R1172S131D-E2-F</b> RICOH RICOH Jun-89</p>	 <p><b>R1172S251B-E2-FE</b> RICOH RICOH HSON-6J</p>	 <p><b>R1172S251B-E2</b> RICOH RICOH HSON-6J</p>

### Hot Parts More

- |                    |                        |                         |                          |                   |
|--------------------|------------------------|-------------------------|--------------------------|-------------------|
| ⚙️ 08052A3R3CAT2A  | ➡️ 08055A102JAT2A      | ➡️ 2220SC223KAT13       | D 2225GC123KAT1A         | ➡️ 7MBR75SB060-03 |
| ⚡️ AN44067A-VF     | ⚙️ AP50T10GI-HF        | D AT24C16N-10SC-2.5     | ➡️ BFP640H6327           | ➡️ BSC265N10LSF   |
| ⚙️ C1608X7R1H471M  | ⚡️ C3225X7R2A225K230AE | ⚙️ CGA7K1X7R3D471M130KA | ➡️ CR2LS-20/UL           | ➡️ CYIFS781BZXCT  |
| D D5V0L1B2LPS-7B   | ⚙️ ELM9748CBA-S        | ⚡️ GCD21BR71H223KA01L   | ⚙️ IRFH8337TRPBF.        | ➡️ IRLR7821       |
| ➡️ LES25A48-1V8REJ | ➡️ LM5100AMX/NOPB      | ⚙️ LM63CIMA             | ⚡️ LQH3N3R9K34M00        | ➡️ M29F200T-90M1  |
| ➡️ M95640-MN6T     | ➡️ MAC221-2            | D MAX3945ETE+T          | ⚙️ MAX5048BAUT+          | ⚡️ MAX812TEUS+T   |
| ⚙️ MB8541P-G       | D MDR150A30            | ➡️ MICROSMD110F-2       | ➡️ MT29F2G08ABAEAH4-IT:E | ➡️ MTP30P06VG     |
| ⚡️ N086RH12        | ⚙️ NP82N055CLE-S12-AZ  | ➡️ PS2761B-1-V-F3       | ➡️ PT2512FK-7W0R1L       | ➡️ RT3T33M-T111-1 |
| ⚙️ SC417AMLTRT     | ⚡️ SI8472DB-T2-E1      | ⚙️ SN74HCT244QPWRQ1     | D SN75ALS192NS           | ➡️ ST330C10C      |
| ➡️ STK621-041      | ⚙️ TC55257DFL-85L      | ⚡️ V24C5C100B2          | ⚙️ W78E52P-24            | ➡️ ZNBG4001       |