



	<h2 style="color: #E67E22;">LB1948MC-ZH</h2>
	<b>Manufacturer Part Number:</b> LB1948MC-ZH
	<b>Manufacturer/Brand:</b> AMI Semiconductor / ON Semiconductor
	<b>Part of Description:</b> IC MOTOR DRIVER PAR 10MFPSK
	<b>Datasheets:</b> <ul style="list-style-type: none"> <li> <a href="#">1.LB1948MC-ZH.pdf</a></li> <li> <a href="#">2.LB1948MC-ZH.pdf</a></li> </ul>
	<b>RoHs Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> <span style="color: green;">Compliant</span> New original, Stock Available.
	<b>Ship From:</b> Hong Kong
Image may be representation. See specs for product details.	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS


### Specifications

Part Number	LB1948MC-ZH
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER PAR 10MFPSK
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	-
Technology	Bipolar
Operating Temperature	-20°C ~ 85°C (TA)
Mounting Type	Surface Mount
Interface	Parallel
Applications	General Purpose
Package / Case	10-LSOP (0.173", 4.40mm Width)
Supplier Device Package	10-MFPSK
Voltage - Supply	2.5 V ~ 16 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	800mA
Output Configuration	Half Bridge (4)
Voltage - Load	2.5 V ~ 16 V
Motor Type - Stepper	Bipolar
Motor Type - AC, DC	Brushed DC
Step Resolution	-
Packaging	Tape & Reel (TR)


LB1948MC-ZH is New Original in Stock, Search LB1948MC-ZH Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1948MC-ZH AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1948MC-ZH : Info@Y-IC.com

### You May Be Also Be interested


**In:**




**LB1948M-TLM**  
SANYO  
SANYO SOP10




**LB1948MC-AH**  
AMI Semiconductor / ON Semiconductor  
IC MOTOR DRIVER PAR 10MFPSK




**LB1950V-TLM-E**  
AMI Semiconductor / ON Semiconductor  
IC MOTOR DRIVER 3PH SL 30SSOP




**LB1948M-TE-LE**  
SANYO  
SANYO SOP10




**LB1948MC-BH**  
AMI Semiconductor / ON Semiconductor  
IC MOTOR DRIVER PAR MFP10S



**LB1950V-TLM**  
SANYO  
LB1950V-TLM SANYO























**LB1948MCGEVB**  
AMI Semiconductor / ON Semiconductor  
BOARD EVAL FOR LB1948MC



**LB194S**  
SANYO  
SANYO HSOP

### Hot Parts

More

- |  |  |  |   |  |
|--|--|--|---|--|
|  22-21/GHC-YR1S2/2C |  250-5700-146     |  ADP3042ARUZ-REEL7  |  ADS7886SDBVR       |  ALT4532-201-T001 |
|  AP7361-33Y-13      |  AUIRS2124STRPBF  |  AX1007E25A         |  BStU68H256         |  BZX384C68-V-GS08 |
|  CD471640B          |  CM2831KIM25      |  CQ0402BRNPO9BN6R2  |  ERA-4SM+           |  F0900VC450       |
|  D FQD13N10LTM      |  GP1UE270RKVF     |  GRB24110D-3W-B     |  GRM1555C1H5R1WA01D |  ICS8304AMLFT     |
|  IRKD71-04          |  KSC945YBU        |  L6391DTR           |  LE9500CBJC-JFG     |  LM2902PWR        |
|  LM4040DIM3-5.0     |  LMX1511TMX/NOPB  |  LP2987IMM-3.3/NOPB |  LTC5505-1ES5#TRPBF |  LTC6244HVIDD#PBF |
|  MAX1481EUB+        |  MAX4104ESA+      |  MAX4218EEE+T       |  MAX706SCSA-T       |  MBR20100CT_HF    |
|  MTD002-LF-00       |  NCP1219AD100R2G  |  NJG1133MD7         |  RKD703KLR1         |  RUR040N02        |
|  S-80814CNNB-B9S-T2 |  S-8424AABFT-TB-G |  S1J-13-F           |  S29GL032N90TFI030  |  SHF-0289Z        |
|  SKB26/06           |  TC72-5.0MUA      |  TD200F10KSC        |  TDA2822G           |  TLZ16B-GS08      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited