










 <p>A Renesas Company</p>	<p>ISL41334IRZ-T7A</p>
	<p>Manufacturer Part Number: ISL41334IRZ-T7A</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC TXRX RS232/485 DL 2PRT 40QFN</p> <p>Datasheets:  ISL41334IRZ-T7A.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	ISL41334IRZ-T7A
Manufacturer	Intersil
Description	IC TXRX RS232/485 DL 2PRT 40QFN
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	40-VFQFN Exposed Pad
Supplier Device Package	40-QFN (6x6)
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS232, RS422, RS485
Number of Drivers/Receivers	2/2
Duplex	Full
Receiver Hysteresis	35mV
Data Rate	20Mbps
Packaging	Tape & Reel (TR)

ISL41334IRZ-T7A is New Original in Stock, Search ISL41334IRZ-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL41334IRZ-T7A Intersil with warrantied and confidence. RFQ ISL41334IRZ-T7A : Info@Y-IC.com

You May Be interested

<p>In:</p>  <p>ISL41387IRZ-T Intersil IC TXRX DUAL PROTOCOL ESD 40-QFN</p>	 <p>ISL41334EVAL1Z Intersil EVALUATION BOARD FOR ISL41334</p>	 <p>ISL41387EVAL1Z Intersil EVALUATION BOARD FOR ISL41387</p>	 <p>ISL41334IRZ Intersil IC TXRX DUAL PROTOCOL ESD 40-QFN</p>
 <p>ISL41387IRZ Intersil IC TXRX DUAL PROTOCOL ESD 40-QFN</p>	 <p>ISL41334IRZ-T Intersil IC TXRX RS232/422/485 40QFN</p>	 <p>ISL4221EIR Intersil IC TXRX RS232 2.7-5.5V ESD 16QFN</p>	 <p>ISL4089IBZ-T7A Intersil IC VIDEO AMP DC-RESTORED 8SOIC</p>

Hot Parts

[More](#)

- | | | | | |
|-------------------|--------------------|----------------------|---------------------|-----------------|
| 04023A390FAT2A | 1206YA103KAT2A | 2MBI100N-060-03 | D AD5816DBCZ-RL7 | BCR16PM-12LB |
| BStH4760 | BSZ115N03CSC | D C0402JB0G102K020BC | C1608C0G1H221J080AA | DDZ9717T-7 |
| EA30QS04-TE16F2 | EVG32T-060 | EXB250-48S1V5-ZJ | F4-75R12KS4 | FDC655BN |
| D GE28F320W18BC60 | GRM0335C2A3R8CA01J | GRM1555C1E9R8DA01D | GRM216R61A225ME24D | HRPF89182B-02TB |
| LD031C271JAB2A | LM1084RS-ADJ | LMT85DCKT | MAX6303ESA+T | MAX640ESA |
| MDC160-12 | NCP508SQ33T1G | PM52AUBZ060-A | PP15-24-28 | QMK432B7334MM-T |
| RPI-441C1 | RS1PJ-M3/84A | RT9193-4GPB | S29GL512P11FFIS10 | SE20FJ-M3 |
| SFH617A-4X001 | SG700U11 | SI2176-B30-GMR | SMAJ4746A-TP | SMF20A-M3-08 |
| SN65C3222DBR | SP490EN-L/TR | STA1037L | D STP8NM60N | TD104N13KOF |
| TR/3216FF1-R | TS2576CM533 | UP0111AMA5 | VCUT05D1-SD0-G4-08 | VI-204-EX |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited