


	<b>15321R-960</b>
	<b>Manufacturer Part Number:</b> 15321R-960
	<b>Manufacturer/Brand:</b> Echelon
	<b>Part of Description:</b> IC TXRX POWER LINE 64LQFP
<b>Datasheets:</b>  15321R-960.pdf	<b>RoHs Status:</b>  Lead free / RoHS
<b>Stock Condition:</b> Compliant New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









**Specifications**

Part Number	15321R-960
Manufacturer	Echelon
Description	IC TXRX POWER LINE 64LQFP
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	PL3150®
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Interface	SPI, UART
Applications	Smart Transceiver
Package / Case	64-LQFP
Supplier Device Package	64-LQFP (10x10)
Voltage - Supply	4.75 V ~ 5.25 V
Core Processor	Neuron
Number of I/O	12
RAM Size	2K x 8
Program Memory Type	EEPROM (512 B)
Controller Series	-
Packaging	Tray

15321R-960 is New Original in Stock, Search 15321R-960 Datasheets, PDF, Inventory at Y-IC.com Online, Order 15321R-960 Echelon with warrantied and confidence. RFQ 15321R-960 : Info@Y-IC.com

You May Be Also Be interested

In:

 Authorized Distributor  <b>153220-2000-RB-WD</b> 3M CONN SKT	  <b>1532195</b> Phoenix Contact CABLE 5POS	 Authorized Distributor  <b>153220-2020-TH</b> 3M CONN SKT 2MM 20POS THRU-BRD SMD	  <b>1532182</b> Phoenix Contact CABLE 5POS
  <b>153220-2020-RB-WC</b> 3M CONN 2MM SKT 20POS THRU-BRD SMD	  <b>15321R-1000</b> Echelon IC SMART TXRX PL 3150 64LQFP	  <b>153220</b> FLIR ADAPTER, 230V FOR 380193	  <b>15321R-5</b> Echelon IC SOC TXRX 64LQFP

Hot Parts

More

- |                    |                |                  |                 |                    |
|--------------------|----------------|------------------|-----------------|--------------------|
| 06035A270DAT2A     | 22255C105KAT2A | 6MBI200FB060     | AP8853-29PL     | BU4211FVE-TR       |
| C4532CH1H104J200KA | CDCU877RHAR    | CRCW0805866RFKEA | D2F-01L30-D3    | DG202BDY           |
| DMTH4004LPS-13     | ELM16400EA-N   | ELM89303BB-S     | FDMC86260       | FQB34N20TM         |
| GJM0335C1E4R7BB01D | HCPL-0211      | HD64F2194F       | IDT71V124SA15YI | IRKD57/12          |
| ISL97646IRZ        | LC72722PM-MPB  | LM25115AMTX      | LQP03TN4N7H02D  | LV25200M-B-MPB-E   |
| M5700-UFA76HYN     | MAX5943AEEE+T  | MIC4101BM        | NCP2890DMR2     | NFA31GD1016R84D    |
| NTGS1135PT1G       | OPA342UA/2K5   | P6SMB7.5A        | RB058LAM-30     | S-8241AAOMC-GAO-T2 |
| SI4686DY-T1-E3.    | SI6946DQ-T1-E3 | SIA811DJ-T1      | SLF7055T-102M   | SN74AUC32RGYR      |
| SP060301M1U5X      | ST280CH08C1    | SW10PCR0xx       | T491C106K016AS  | TD170N18KOF        |
| TISP3219T3BJR      | TPS79330DBVRG4 | TSF20H120C       | V300C12H150BS   | VESD05A6-HA3-GS08  |