

	ICS952911BF	
	Manufacturer Part Number:	ICS952911BF
	Manufacturer/Brand:	IDT (Integrated Device Technology)
	Part of Description:	IC CLOCK CTRL HUB P4 48SSOP
	Datasheets:	 ICS952911BF.pdf
	RoHs Status:	Contains lead / RoHS non-compliant
	Stock Condition:	New original, 530 pcs Stock Available.
	Ship From:	Hong Kong
	Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.		









Specifications

Part Number	ICS952911BF
Manufacturer	IDT (Integrated Device Technology)
Description	IC CLOCK CTRL HUB P4 48SSOP
Category	Integrated Circuits (ICs) > Clock/Timing - Application
Part Status	530 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Frequency - Max	-
Package / Case	48-BSSOP (0.295", 7.50mm Width)
Supplier Device Package	48-SSOP
Number of Circuits	-
Voltage - Supply	3.3V
Output	Clock
Main Purpose	-
Input	-
PLL	-
Ratio - Input:Output	-
Differential - Input:Output	-
Packaging	Tube

ICS952911BF is New Original in Stock, Search ICS952911BF Datasheets, PDF, Inventory at Y-IC.com Online, Order ICS952911BF IDT (Integrated Device Technology) with warrantied and confidence. RFQ ICS952911BF : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>ICS952911BFT IDT (Integrated Device Technology) IC CLOCK CTRL HUB P4 48SSOP</p>	 <p>ICS952911BFLFT ICS ICS952911BFLFT ICS</p>	 <p>ICS952906BGLFT IDT ICS952906BGLFT IDT</p>	 <p>ICS952930DF ICS ICS952930DF ICS</p>
 <p>ICS952906BFLFT IDT ICS952906BFLFT IDT</p>	 <p>ICS953002CF IDT (Integrated Device Technology) IC TIMING CTRL HUB P4 56-SSOP</p>	 <p>ICS952911BFLF ICS ICS952911BFLF ICS</p>	 <p>ICS952909BKLFT IDT (Integrated Device Technology) IC TIMING CTRL HUB P4 56-VFQFPN</p>

Hot Parts

More

- | | | | | |
|------------------------|----------------------|-----------------------|-----------------------|----------------------|
| ⊕ 2225AA102JAT1A | ↔ ADP2384ACPZN-R7 | ⇒ AZ431BM-AE1 | D BCP53LT1 | ⇒ BZT52-C18S |
| ⊖ BZX84T2162.4A | ⊕ C1005JB1A335M050BC | D C1608X7R1A225K080AC | ⇒ C2012C0G2A472K125AA | ⇒ CL-482T-WSR-SD-TS |
| ⊕ CLLE1AX7R1A154M050AC | ⊖ D1901N3600T | ⊕ DAC5573IPW | ↔ DFLU1400-7-F | ⇒ DTC123JKA |
| D GRM1555C1E391JA01D | ⊕ GRM1555C1H6R0BA01J | ⊖ GRM1885C1H1R8CA01D | ⊕ HUF76429D3S | ⇒ HUR2X30-30 |
| ⇒ LD035C222KAB2A | ↔ LM26CIM5-YPE | ⊕ LM39501R-5.0 | ⊖ LMX2581SQ/NOPB | ⇒ LT1999HS8-10#TRPBF |
| ↔ LTC1756EGN#TRPBF | ⇒ MBRD650TRPBF | D MCT5200300 | ⊕ MIG20J105LB | ⊖ MLF1608D82NMTA00 |
| ⊕ MSMLJ40CAE3 | D MTC25A1600V | ⇒ NLC322322T-220K | ↔ PCD50912H/A95/2 | ⇒ QS3VH800Q |
| ⊖ R920212000 | ⊕ RT9167A-15GB | ↔ SBRD835LT4G | ⇒ SC431LCSK-1TR | ⇒ SI3054-E-ZS5R |
| ⊕ SI4814DY-T1-E3 | ⊖ SIA444DJT-T1-GE3 | ⊕ SML-210LTT86M | D SMS7621-006LF | ⇒ ST72F324J4T6 |
| ↔ TFM201610ALMA1R5MTAA | ⊕ TL4050B50QDBZRQ1 | ⊖ TMP89FM42AUG | ⊕ UPD75P4308GS | ⇒ V48C5T50AL |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited