


 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">HI4P0509-5</h2>	
	<p>Manufacturer Part Number: HI4P0509-5</p>	
	<p>Manufacturer/Brand: Intersil</p>	
	<p>Part of Description: IC MULTIPLEXER DUAL 4X1 20PLCC</p>	
	<p>Datasheets:  HI4P0509-5.pdf</p>	
	<p>RoHs Status: Contains lead / RoHS non-compliant</p>	
	<p>Stock Condition: New original, 38 pcs Stock Available.</p>	
	<p>Ship From: Hong Kong</p>	
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>	

Specifications

Part Number	HI4P0509-5
Manufacturer	Intersil
Description	IC MULTIPLEXER DUAL 4X1 20PLCC
Category	Integrated Circuits (ICs) > Interface - Analog Switches,
Part Status	38 pcs Stock
Series	-
Operating Temperature	0°C ~ 75°C (TA)
Package / Case	20-LCC (J-Lead)
Supplier Device Package	20-PLCC (9x9)
Number of Circuits	2
-3db Bandwidth	-
Multiplexer/Demultiplexer Circuit	4:1
Switch Circuit	SP4T
On-State Resistance (Max)	400 Ohm
Voltage - Supply, Single (V+)	-
Voltage - Supply, Dual (V±)	±15V
Channel-to-Channel Matching (ΔRon)	20 Ohm
Switch Time (Ton, Toff) (Max)	250ns, 250ns (Typ)
Charge Injection	-
Channel Capacitance (CS(off), CD(off))	10pF, 12pF
Current - Leakage (IS(off)) (Max)	30pA (Typ)
Crosstalk	-
Packaging	Tube

HI4P0509-5 is New Original in Stock, Search HI4P0509-5 Datasheets, PDF, Inventory at Y-IC.com Online, Order HI4P0509-5 Intersil with warrantied and confidence. RFQ HI4P0509-5 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>HI4P0546-5 Intersil IC MULTIPLEXER 16X1 28PLCC</p>	 <p>HI4P0506-5 Intersil IC MULTIPLEXER 16X1 28PLCC</p>	 <p>HI4P0508-5 INTERSI INTERSI PLCC</p>	 <p>HI4P0509-5Z96 Intersil IC MULTIPLEXER DUAL 4X1 20PLCC</p>
 <p>HI4P0509-5Z Intersil IC MULTIPLEXER DUAL 4X1 20PLCC</p>	 <p>HI4P0507-5 INTERSI INTERSI PLCC</p>	 <p>HI4P0547-5 Intersil IC MULTIPLEXER DUAL 8X1 28PLCC</p>	 <p>HI4P0201-5Z Intersil IC SWITCH QUAD SPST 20PLCC</p>

Hot Parts

More

<p>⊕ 06033D105KAT2A</p> <p>⊖ AP1506-50</p> <p>⊕ C1608C0G2E391K080AA</p> <p>D ELM7530NBA-S</p> <p>⇒ IRGTDDB200K12</p> <p>⊖ LQW2BHNR15J01L</p> <p>⊕ MG5026ES40</p> <p>⊖ PQ1CG41H2RZH</p> <p>⊕ STA333MLJ13TR</p> <p>⊖ TD121N12K0F</p>	<p>⊖ 12061C512JAT2A</p> <p>⊕ AT25128A-10TU-2.7</p> <p>⊖ CDBM120-HF</p> <p>⊕ ET5333SC</p> <p>⊖ IRLML6402TRFPBF</p> <p>⇒ LT06YD475MAT2W</p> <p>D NCS20062DR2G</p> <p>⊕ PTFA180701E</p> <p>⊖ STD1703LT4</p> <p>⊕ TUSB1106GRTR</p>	<p>⇒ 16253713</p> <p>D BT136S-600D</p> <p>⊕ CIM-112S7R1-T</p> <p>⊖ FP06R12W1T4-B3</p> <p>⊕ IXTH360N055T2</p> <p>D M27C2001-15F1</p> <p>⇒ NP88N04KUG</p> <p>⊖ RHRD660S9A-F085</p> <p>⊕ STV0299BLT</p> <p>⊖ UQCL2A2R4BAT2A/500</p>	<p>D 302R29N221JV4E-220PJ/3000V</p> <p>⇒ BU4834FVE-TR</p> <p>⊖ DALC208SC</p> <p>⊕ GRM1556P1H6R6DZ01D</p> <p>⊖ KD70F-40</p> <p>⊕ MC74AC373DTR2</p> <p>⊖ PEX8532-BA25BI</p> <p>⇒ SMP1343-007</p> <p>D T130N1600BOF</p> <p>⊕ V24C24T100AN</p>	<p>⇒ A1205S-W25</p> <p>⇒ BZX584-C5V6</p> <p>⇒ ELM34814AA</p> <p>⇒ GRM1557U1H8R4DZ01D</p> <p>⇒ LD051A100GAB2A</p> <p>⊖ MCIMX515DJM8C</p> <p>⇒ PM30-24S12</p> <p>⇒ SP0502BAHTG</p> <p>⇒ T520V477M2R5ATE006</p> <p>⇒ Z0107MA</p>
--	--	--	--	---

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited