

	<b>TDA16846-2</b>	
	<b>Manufacturer Part Number:</b>	TDA16846-2
<b>Manufacturer/Brand:</b>	INFINEONT	
<b>Part of Description:</b>	TDA16846-2 INFINEONT	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 24 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

### Specifications

Part Number	TDA16846-2
Manufacturer	INFINEONT
Description	TDA16846-2 INFINEONT
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	24 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

TDA16846-2 is New Original in Stock, Search TDA16846-2 Datasheets, PDF, Inventory at Y-IC.com Online, Order TDA16846-2 with warrantied and confidence. RFQ TDA16846-2 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>TDA16846-2G</b> Infineon Infineon SOP14	 <b>TDA16846</b> INFINEO TDA16846 INFINEO	 <b>TDA16833G</b> INFINEON TDA16833G INFINEON	 <b>TDA16834</b> INFINEON TDA16834 INFINEON
 <b>TDA168462HKLA1</b> International Rectifier (Infineon Technologies) IC POWER SUPPLY CONTROLLER 14DIP	 <b>TDA16832G</b> INFINEON TDA16832G INFINEON	 <b>TDA16833</b> 0628L+ TDA16833 0628L+	 <b>TDA168462GGEGHUMA1</b> International Rectifier (Infineon Technologies) IC POWER SUPPLY CONTROLLER DSO14

### Hot Parts

More

- |                       |                      |                      |                    |                      |
|-----------------------|----------------------|----------------------|--------------------|----------------------|
| ⊛ 06035U1R2CAT2A      | ↔ 0805YC394K4T2A     | ⇒ AAT3663IWO-4.2-1   | D ADA4891-1ARJZ-RL | ⇒ BC847B-13-F        |
| ⊣ BZX84B15-GS08       | ⊛ C3216CH2W153J160AA | D CL10C471JB8NNWC    | ⇒ CL1225SNA1       | ⇒ CY27022SCT         |
| ⊛ CY7C1021CV33-10ZXIT | ⊣ DD240KC40          | ⊛ DD82S06K-K         | ↔ DTD122JK         | ⇒ ESDALCL6-2SC6      |
| D FDP7N60NZ           | ⊛ FM1073V-23-G       | ⊣ FQA48N20           | ⊛ GFF200E12        | ⇒ GJM1555C1H3R0CB01D |
| ⇒ GQM1555C2D8R6WB01D  | ↔ GRM1555C1H4R7BZ01J | ⊛ GRM1555C1H5R4DZ01D | ⊣ IXFX32N90P       | ⇒ K4X56163PG-LGC3    |
| ↔ LTC1283ACN          | ⇒ M29DW323DT-70ZE6E  | D MAMK2520T1R0M      | ⊛ MAX312FESE+      | ⊣ MC78M12BDTG        |
| ⊛ MIC2297-38YML       | D MIC5255-2.7YM5     | ⇒ MMU01020D3302CB300 | ↔ MT5389FFFU       | ⇒ MURS240-E3/52T     |
| ⊣ MX674AKN+           | ⊛ NTMFS4121NT1G      | ↔ PCMB051B-6R8MS     | ⇒ RQK0603CGDQATL-H | ⇒ SM20CXC915         |
| ⊛ SMC3K33CAHE3/57     | ⊣ SN74AHCT373DBR     | ⊛ SN74LVC1G3157DSFR  | D SPM0102ND3-3     | ⇒ TC74AC32P          |
| ↔ TPS3809I50DBVR      | ⊛ V300C28M150AL      | ⊣ VI-213-EU          | ⊛ XC61CN2402PRN    | ⇒ XP152A12COMR-G     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited