

 Not Actual Photo YIC International Co., Limited.	<b>2SJ646-TL</b>
	<p><b>Manufacturer Part Number:</b> <a href="#">2SJ646-TL</a></p> <p><b>Manufacturer/Brand:</b> SANYO</p> <p><b>Part of Description:</b> SANYO TO-252</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 2500 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
Image may be representation. See specs for product details.	

### Specifications

Part Number	2SJ646-TL
Manufacturer	SANYO
Description	SANYO TO-252
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

2SJ646-TL is New Original in Stock, Search 2SJ646-TL Datasheets, PDF, Inventory at Y-IC.com Online, Order 2SJ646-TL with warrantied and confidence. RFQ 2SJ646-TL : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>2SJ647-T1</b> NEC 2SJ647-T1 NEC	 <b>2SJ648</b> NEC 2SJ648 NEC	 <b>2SJ647-T1-A</b> NEC/RENESAS 2SJ647-T1-A NEC/RENESAS	 <b>2SJ645-TL-E</b> ON 2SJ645-TL-E ON
 <b>2SJ645-E</b> Original 2SJ645-E Original	 <b>2SJ645</b> S 2SJ645 S	 <b>2SJ646-N-TL-E</b> ON 2SJ646-N-TL-E ON	 <b>2SJ646-TL-E</b> SANYO 2SJ646-TL-E SANYO

### Hot Parts

More

- |                        |                   |                   |                        |                       |
|------------------------|-------------------|-------------------|------------------------|-----------------------|
| ⊛ 06033C182JAT4A       | ➤ 0603YG103ZAT2A  | ➤ 6MBI30F060      | D AP1333U-HF           | ➤ AP7335-39WG-7       |
| ⊣ AT90SC3232CS-AL      | ⊛ ATTINY15L-1SI   | D BC857AW-7-F     | ➤ BCM3350KPB           | ➤ BLD6G22L-150BN/2    |
| ⊛ CGA2B2X8R1H472K050BE | ⊣ CL05C160JB51PNC | ⊛ CY2220PVC-1     | ➤ DD90N16L             | ➤ DEA162400HT-8004B1  |
| D DMG3414UQ-7          | ⊛ DSEP2*101-04A   | ⊣ DTA124XU        | ⊛ FAN1540MPX           | ➤ FDMA2002NZ          |
| ➤ GRM0336R1E5R8DD01D   | ➤ GT60M302        | ⊛ HMK212B7473KG-T | ⊣ IMH21T110            | ➤ IXFH32N50           |
| ➤ LD39115J18R          | ➤ LM4132BMF-1.8   | D LP2954AISX      | ⊛ LT3684EDD#PBF        | ⊣ MAX1111AEPE+        |
| ⊛ MMZ1608R300ATA00     | D OPA2333AIDGKRG4 | ➤ PBMB75A6        | ➤ PFC-W0805LF-03-1503B | ➤ PI3L720ZHE          |
| ⊣ QM200E2Y-HB          | ⊛ RA203220        | ➤ RFP4N05L        | ➤ RT9013-12GB          | ➤ S-8351A30MC-J2P-T2G |
| ⊛ SF20D600D2           | ⊣ SI7949DP-T1-GE3 | ⊛ SK60GAL128      | D SMV1705-079LF        | ➤ SN74LS04DR          |
| ➤ SST29SF040-55-4C-WH  | ⊛ STAC9751TR-CC1  | ⊣ TPS76901QDBVRQ1 | ⊛ VI-264-EU-03         | ➤ XI-ARM-C22          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited