









	<h2 style="color: red;">BC63B239A04-IYB-E4</h2>
	<p>Manufacturer Part Number: BC63B239A04-IYB-E4</p> <p>Manufacturer/Brand: CSR PLC (Qualcomm)</p> <p>Part of Description: IC RF TXRX+MCU BLUETOOTH 51WLCSP</p> <p>RoHs Status:  Lead free / RoHS Compliant</p> <p>Stock Condition: New original, 7414 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	BC63B239A04-IYB-E4
Manufacturer	CSR PLC (Qualcomm)
Description	IC RF TXRX+MCU BLUETOOTH 51WLCSP
Category	RF/IF and RFID > RF Transceiver ICs
Part Status	7414 pcs Stock
Series	BlueCore®
Frequency	2.4GHz
Operating Temperature	-
Type	TxRx + MCU
Sensitivity	-
Package / Case	51-WLCSP
Voltage - Supply	2.7 V ~ 5.5 V
Power - Output	7dbm
Memory Size	6MB ROM, 48kB RAM
Protocol	Bluetooth v2.1 +EDR, Class 2 and 3
Data Rate (Max)	3Mbps
Serial Interfaces	-
Current - Receiving	-
RF Family/Standard	Bluetooth
Modulation	-
Current - Transmitting	-
Packaging	Original-Reel®

BC63B239A04-IYB-E4 is New Original in Stock, Search BC63B239A04-IYB-E4 Datasheets, PDF, Inventory at Y-IC.com Online, Order BC63B239A04-IYB-E4 CSR PLC (Qualcomm) with warrantied and confidence. RFQ BC63B239A04-IYB-E4 : Info@Y-IC.com

You May Be Also Be interested In:

 <p>BC63B239A04-IQD-E4 CSR PLC (Qualcomm) IC RF TXRX+MCU BLUETOOTH 40-QFN</p>	 <p>BC63B239A05-AQK-E4 CSR PLC (Qualcomm) IC RF TXRX+MCU BLUETOOTH 40UFQFN</p>	 <p>BC63B239A04-AQK-E4V CSR CSR QFN</p>	 <p>BC63B329A04U CSR BC63B329A04U CSR</p>
 <p>BC63B239A04U CSR BC63B239A04U CSR</p>	 <p>BC63B239A04AU CSR BC63B239A04AU CSR</p>	 <p>BC63B239A04-IKB-E4S CSR BC63B239A04-IKB-E4S CSR</p>	 <p>BC63B239A04-IUE-E4 CSR PLC (Qualcomm) IC RF TXRX+MCU BLUETOOTH 51WLCSP</p>

Hot Parts

More

- | | | | | |
|---|---|--|---|--|
| <ul style="list-style-type: none"> ⚙ 1206YC824KA12A ⚡ BC6-7974-PIC ⚙ BC6140A02-IQQB-R D BC638+126 ➔ BC63B239A04-AQK-E4 ⚡ BC63B239A05-AQK-E4 ⚙ BC6888A04-ICXL-R ⚡ FMA11AT148 ⚙ NLHV25T-R27J-EFD ⚡ SCD03021T-470M-N | <ul style="list-style-type: none"> ⚡ 2FI100A-030N ⚙ BC6-7974-PIC-A ⚡ BC6145A04-IQQB-R ⚙ BC638-16 ⚡ BC63B239A04-IKB-E4 ➔ BC63C159A03 D BC6930QJT1 ⚙ HYB18L256169BF-7.5 ⚡ NTP6410ANG ⚙ UQCFVA181JAT2A\500 | <ul style="list-style-type: none"> ➔ 2MBI300L-120 D BC6110A14 ⚙ BC6150A08-IQQF-R ⚡ BC639-10 ⚙ BC63B239A04-IKB-E4S D BC63C159A03-IQB-E4 ➔ BR24C04N-10SU-1.8 ⚡ MAX16029TG+T ⚙ PD70210AILD-TR ⚡ VI-24M-CX | <ul style="list-style-type: none"> D AIC1117A-50CY ➔ BC6110A14U ⚡ BC636-16 ⚙ BC639-16 ⚡ BC63B239A04-IQD-E4 ⚙ BC63C159A03U ⚡ C2012JB1E475K125AB ➔ MC145040DW D S-80926ANMP-DDP-T2 ⚙ VI-252-CW/F2 | <ul style="list-style-type: none"> ➔ BA5972FP ➔ BC6130A04-IQQB-R ➔ BC637-16 ➔ BC639-16ZL1G ➔ BC63B239A04U ⚡ BC6888A04-ICJG-RL ➔ ESD200-B1-CSP0201 ➔ NCV8403STT1G ➔ SBR3U30P1-7-F ➔ XC6210A152M |
|---|---|--|---|--|

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited