


	<h2 style="color: red;">LC78615E-01US-H</h2>
 Not Actual Photo YIC International Co., Limited.	<b>Manufacturer Part Number:</b> LC78615E-01US-H
	<b>Manufacturer/Brand:</b> AMI Semiconductor / ON Semiconductor
	<b>Part of Description:</b> IC SERVO PROC LSI CD-DSP 64QFP
	<b>Datasheets:</b>  <a href="#">LC78615E-01US-H.pdf</a>
	<b>RoHs Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, Stock Available.
<b>Ship From:</b> Hong Kong	
<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS	









### Specifications

Part Number	LC78615E-01US-H
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC SERVO PROC LSI CD-DSP 64QFP
Category	Integrated Circuits (ICs) > Audio Special Purpose
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Specifications	-
Number of Channels	1
Interface	Serial
Applications	Consumer Audio
Package / Case	64-BQFP
Supplier Device Package	64-PQFP (14x14)
Voltage - Supply	3 V ~ 3.6 V
Function	Audio Signal Processor
Packaging	Tray

LC78615E-01US-H is New Original in Stock, Search LC78615E-01US-H Datasheets, PDF, Inventory at Y-IC.com Online, Order LC78615E-01US-H AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LC78615E-01US-H : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>LC7860KA</b> SANYO LC7860KA SANYO	 <b>LC7861KE</b> SANYO LC7861KE SANYO	 <b>LC78610EH-E</b> SANYO LC78610EH-E SANYO	 <b>LC78620E-D</b> SANYO LC78620E-D SANYO
 <b>LC7861</b> SANYO LC7861 SANYO	 <b>LC7861N</b> SANYO LC7861N SANYO	 <b>LC78605E-E</b> SANYO LC78605E-E SANYO	 <b>LC78621ED</b> SANYO LC78621ED SANYO

### Hot Parts

[More](#)

- |                           |                     |                       |                     |                        |
|---------------------------|---------------------|-----------------------|---------------------|------------------------|
| ⊕ 0201YC221JAT2A          | ↔ 08051U470FAT2A    | ⇒ 1206GC221KAT1A      | D 74438334068       | ⇒ ADM6315-44D2ARTZR7   |
| ⊖ BTB24-600BRG            | ⊕ BZX84C18LT1G      | D C1005NP01H150J050BA | ⇒ CBT3245APW        | ⇒ CGJ5L2X7R0J335K160AA |
| ⊕ CY7C65621-56LTXCT       | ⊖ DLT1130A          | ⊕ FDP8870_F085        | ↔ FQD8P10TM_F085    | ⇒ GRM155C80J225ME95D   |
| D GT50J324                | ⊕ HD64F2643FC25     | ⊖ IRKD61-18           | ⊕ IXFK50N85X        | ⇒ JTF33-013 AMP-T03    |
| ⇒ LE79489-2JC             | ↔ LM4040DEM3-2.1+T  | ⊕ LM5025SDX           | ⊖ LMR62421XSD/NOPB  | ⇒ LTC015EEB            |
| ↔ LTC3411EDD#TRPBF.       | ⇒ LTC6088CDHC#TRPBF | D LTC6101ACMS8#TRPBF  | ⊕ LTC6803IG-1#TRPBF | ⊖ M30623M4T-928GP      |
| ⊕ MB3793-27APFV-G-JN-EF-6 | D MC33267D2T        | ⇒ MC35XS3400D         | ↔ MM1385DNRE        | ⇒ MP1010BEF-C107-LF-Z  |
| ⊖ NRV2012T4R7MGF          | ⊕ PSCH85/06         | ↔ PSS10S51F6          | ⇒ RT9284B-15PJ6     | ⇒ SKM500GA176D         |
| ⊕ SKY65404-21             | ⊖ ST380C04C0        | ⊕ STP2N80FI           | D TCR2EF33.LM       | ⇒ TMK063CG3R3CT-F      |
| ↔ TPS2057ADR              | ⊕ TPS2115PWR        | ⊖ TPS61175PW          | ⊕ UC2825BDW         | ⇒ Z0107NN5AA4          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited