


	<p>S-1009C38I-N4T1U</p>
	<p>Manufacturer Part Number: S-1009C38I-N4T1U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR</p>
	<p>Datasheets:  S-1009C38I-N4T1U.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>



Specifications

Part Number	S-1009C38I-N4T1U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-1009
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	3.8V
Packaging	Tape & Reel (TR)

S-1009C38I-N4T1U is New Original in Stock, Search S-1009C38I-N4T1U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-1009C38I-N4T1U SII Semiconductor Corporation with warrantied and confidence. RFQ S-1009C38I-N4T1U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-1009C39I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C37I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C37I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C40I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>
 <p>S-1009C37I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C39I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C38I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C38I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>

Hot Parts

More

- | | | | | |
|---------------------------|--------------------|---------------------|----------------------|-------------------|
| ⊛ 04023U2R4CAT2A | ↔ 12065C474K4T2A | ⇒ 1206YC105KAJ2A | D 1808CA470KAT1A | ⇒ AP3842GP-E1 |
| ⊣ AT24CS64-SSHM-T | ⊛ AT88SC6416C-SU | D BAV99BRLP-7 | ⇒ BZD27C33P-M-08 | ⇒ CVR-42A-221SW1 |
| ⊛ CXA2027Q. | ⊣ DG413LDQ-T1-E3 | ⊛ ELM88121CA-S | ↔ FDS7296N3 | ⇒ FS18SM-10 |
| D GRM1555C1HR60CA01D | ⊛ H11AV2.300 | ⊣ IDT74F646ATSO | ⊛ KSA928A-YTA | ⇒ LGC24Z225MAT2S1 |
| ⇒ LM324NSR-A | ↔ LM3500TLX-16 | ⊛ M95128-WMN6TPPSB | ⊣ MB81C4256A-70PJ-FG | ⇒ MBRD1045T4G |
| ↔ NJM2871BF33 | ⇒ NP48N055MLE | D PD175V2U75 | ⊛ PIC18F66J90T-I/PT | ⊣ PM8389-NI |
| ⊛ PSB25/02 | D PT7M6129NLC4EX | ⇒ RJK03B9DPA-00-J5A | ↔ S-8241ABDPN-KBDTFG | ⇒ SHP1045P-F680A |
| ⊣ TDA9351PS/N2/1I0675 | ⊛ TK55S10N1 | ↔ TLS2271BB.BZ | ⇒ TLV1117CKVURG3 | ⇒ TMS570LS |
| ⊛ TPD1047F. | ⊣ TPS3106K33DBVRG4 | ⊛ TPS61140DRCR | D TPS68420YFDR | ⇒ TT61N12LOF |
| ↔ U2731B-NFNG1/U2731B-NR6 | ⊛ V10P15-M3/H | ⊣ VI-2N1-MU | ⊛ VLF3010AT-1R5N1R2 | ⇒ XBS053V13R |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited